

Packing list in the box

Installation instructions

OMG V2-S





Packing list in the box






OMG V2-S C Copper wire feed gear

OMG V2-S S

Steel wire feed gear

Installation instructions




Step 2 Hot bed Z axis 2









Extrusion of long-distance filament feeding process



