


If the left-side light strip fails to light up





Remove the front glass panel carefully




It is very likely that there is an issue with the connecting wire here.




Press down the pressure plate and pull out the connecting wire






If the ribbon cable becomes loose or disconnected



Align the ribbon cable with the socket and press it firmly into the connector.

Please note the orientation of the cable end when plugging it in, follow the direction shown in the picture.





After proper installation, this is the final result:
The cable end cannot be pulled out when
tugging both ends.



Reconnect the wire and
reinstall the front glass panel.

