

LOCAL AIRPORT OPERATIONS

This checklist can be used when you intend to return to the same airport. Complete the TGT Normal checklist through Taxi then transition to this checklist. This checklist based off of TGT Normal G280 Checklist v3.1 Sep 2023

BEFORE TAKEOFE

BEFURE TAKEUFF		
Cockpit Displays	SET	
WINDSHIELD HEAT	AS REQUIRED	
Anti-ice	AS REQUIRED	
EICAS	*CHECKED*	
LIGHTS	SET (EXTERIOR & CABIN SIGNS)	
PROBE HEATAUTO	/ OVRD (IF ICING CONDITIONS)	
Headings	*CHECKED RWY XX*	
END		
CLIMB		
Landing Gear	UP and LOCKED	
At VSE -10 minimum and accelerating:		
Flaps	UP	
Climb Thrust	SET (CLB)	
Lights	SET	
Probe Heat	AUTO	

END

TRAFFIC PATTERN

FMS Arrival and Approach	PROGRAMMED
HUD Data	SET
HUD / EVS	*CHECKED
Landing Data	BRIEFED
Autobrakes	AS REQUIRED
Avionics	*AS REQUIRED*(SOURCE & COURSE)
Baro Mins	*AS REQUIRED*
Cockpit Displays	SET
Approach Brief	*COMPLETE
	END

BEFORE LANDING

Landing Gear	*DOWN / THREE GREEN*
Flaps	LND
Airspeed	V тgт
Lights	SET
EICAS	*CHECKED*

END



TAXI BACK

Flaps	AS REQUIRED
Lights	SET
Times and Fuel	RECORDED and CHECKED
FMS	INITIALIZED / PROGRAMMED
V-Speeds (T/O & LDG)	CHECKED / SET
TRIMS	*X.X / 0 / 0
AUTOBRAKE	RTO
Thrust Mode	TO/GA
PFD Scan (Vspds, FMA, NAV SRC)	AS REQUIRED
T/O Box	CONFIRMED
Flaps	*AS REQUIRED*
Brake Temps	CHECKED
Wx Radar	ON
Takeoff and Approach Briefings	*COMPLETE

GO-AROUND (TWO ENGINE)

TO/GA Button	PRESS
Airspeed	VREF
Thrust	GO-AROUND THRUST (IF REQUIRED)
FLAPS	20°
Once go-around attitude and both established with flaps a Landing Gear	•
At safe altitude: Vertical Mode	MAN SPEED / 180 KTS / FLC
At Airspeed VREF + 20 KTS	or greater: UP
Thrust	AS REQUIRED
	END