
Display adapter: Top copper - component-side reference

Material Weight Calculator R2 - 70 x 18 mm board - print 100%, no fit-to-page




Black is retained copper. Use Gerbers for factory fabrication. Two layers require registration.

100 mm scale check

Display adapter: Top copper - MIRRORED toner-transfer mask

Material Weight Calculator R2 - 70 x 18 mm board - print 100%, no fit-to-page




Black is retained copper. Use Gerbers for factory fabrication. Two layers require registration.

100 mm scale check

Display adapter: Bottom copper - viewed from underside

Material Weight Calculator R2 - 70 x 18 mm board - print 100%, no fit-to-page




Black is retained copper. Use Gerbers for factory fabrication. Two layers require registration.

100 mm scale check

Display adapter: Bottom copper - toner-transfer mask

Material Weight Calculator R2 - 70 x 18 mm board - print 100%, no fit-to-page



Black is retained copper. Use Gerbers for factory fabrication. Two layers require registration.

100 mm scale check