






FAULT PIN WILL GO LOW WHEN THERMAL SHUTDOWN OR OVERCURRENT



## CONTROL

INT 1 - INPUT 1, CONTROLS STATE OF M1 INT 2 - INPUT 2, CONTROLS STATE OF M2

PWM SPEED CONTROL

xIN1 xIN2 FUNCTION

PWM 0 FORWARD PWM, FAST DECAY
1 PWM FORWARD PWM, SLOW DECAY
0 PWM REVERSE PWM, FAST DECAY
PWM 1 REVERSE PWM, SLOW DECAY

OPERATING CONDITIONS

VBATT 2.7 to 10.8 V
DIGITAL INPUTS 0.0 to 5.75 V
CONTINUOUS CURRENT 2 A
PEAK CURRENT 4 A

