


## FAN screws and spacers assembly




Mounted from PCB top  
through FAN hole M3x 3  
ex. MECH34

Mounted from  
PCB top

**Spacer sleeve M3 x 3  
ex. MECH32**


Mounted from PCB bottom Screw M3 x 3  
ex. MFCH40



## Screw position on the FAN

FAN blowing direction.  
Arrow MUST be facing  
down (on the PCB)

#### **FAN wire orientation**



# Assembly bottom

