

FAN screws and spacers assembly




Mounted from PCB top through FAN hole M3x3
ex. MECH34

Mounted from PCB top

Spacer sleeve M3x3
ex. MECH37

Mounted from PCB bottom Screw M3x3
ex. MECH40

FAN orientation and screw position



FAN wires must face top of the board and connector J27

J27

FAN wire orientation
FAN wires



Crimp ends with
MECH23, MECH24,
MECH25

Assembly bottom

