


Mounted from PCB top  
through FAN hole M3x3  
ex. MECH34

Mounted from  
PCB top

Spacer sleeve M3 x 3  
ex MFCH32

Mounted from PCB bottom ex. MECH40 Screw M3 x 3

#### TAN orientation and screw position




Screw  
position  
on the FAN

FAN blowing direction.  
Arrow MUST be facing  
down (on the PCB)

AN wires  
ust face top  
f the board  
nd  
onector J27

## wire orientation



PCB

Crimp ends with  
MECH23, MECH24,  
MECH25

## Assembly bottom

