

QER- 10535

QER: MERAKES EAST PROJECT SF216608C002.03 – Longitudinal scratches on zeta wire

Rev 0



Pipe section / Details

Item	Traceability / identification
Project number	SF216608C002
Project name	MERAKES EAST PROJECT
Pipe section	SF216608C002.03
ST number	ST254.72048
Affected layer / equipment	Zeta vault spiralling
Length affected	386.4m till 386.7m.
Drawing number / MP code / STA / Dimension	ZETA 12 FI 11(MP746)

Overview of anomaly

Problem Description :-

During the zeta spiraling of MERAKES EAST PROJECT SF216608C002.03 (ST254.72048), longitudinal scratches on zeta wire was detected at length 386.4m till 386.7m.

The details of measurement are as per below.

- Depth: 129um
- Upsetting: N/A

Root Cause :-

The root cause was due to the roller phosphating coating is not suitable for FI11 wire grade.

Problem Handling:-

According to project acceptance criteria CD_216608C002_str25472048_TR01-09_rev0_An_Pressure vault, the maximum allowable criteria for the depth of longitudinal scratch in red areas is 300um and for the maximum upsetting is 50um. Thus, this defect was accepted as it is.

Defect Photo




Figure 1 : Longitudinal scratches on zeta wire was detected at length 386.4m till 386.7m.

Plastic copy measurement



Figure 2 : According to project acceptance criteria CD_216608C002_str25472048_TR01-09_rev0_An_Pressure vault, the maximum allowable criteria for the depth of longitudinal scratch in red areas is 300um and for the maximum upsetting is 50um. Thus, this defect was accepted as it is.

Defect Photo



Figure 3 : Longitudinal scratches on zeta wire was detected at length 386.4m till 386.7m.

Plastic copy measurement



Figure 4 : According to project acceptance criteria CD_216608C002_str25472048_TR01-09_rev0_An_Pressure vault, the maximum allowable criteria for the depth of longitudinal scratch in red areas is 300um and for the maximum upsetting is 50um. Thus, this defect was accepted as it is.

THANK YOU

