This documentation and its accompanying audio file by Martin Zuther is licensed under a <u>Creative Commons Attribution-ShareAlike 4.0</u> International License.

FLAC-compressed wave file (44.1 kHz, 24 bit, stereo)

Please verify correctness of signal meters visually.

00:00.000 - 00:02.000 silence

00:02.000 - 00:05.000 sine wave (997 Hz)

[left channel: -60.10 dB FS peak] [right channel: -59.90 dB FS peak]

[left signal meter should not light] [right signal meter should

00:05.000 - 00:07.000 silence

00:07.000 - 00:17.000 sine wave (997 Hz, volume sweep)

[left channel: -60.10 dB FS to -20.10 dB FS peak] [right channel: -19.90 dB FS to -59.90 dB FS peak]

[left signal meter should lightl [right signal meter should light]

00:17.000 - 00:19.000 silence

00:19.000 - 00:19.100 sine wave burst (997 Hz)

[left channel: -0.10 dB FS peak]

[right channel: +0.00 dB FS peak, clipped waveform]

light] [left signal meter should ιιεττ signal meter should [right signal meter should light]

00:19.100 - 00:21.100 silence

Validation settings

File: signal_meters_stereo.flac

Host SR: 44 100 Hz

Channel: All

Display:

[] Peak meter level[] Average meter level