


ESP32 DC motor speed controller — intended wiring (6 V N20 gearmotor)


Pins are proposed. The firmware currently simulates the motor and uses only


GPIO23 (loop timing) and UART0; the other pins are not driven yet.







































J2 pin order is typical for N20 hall-encoder motors: check yours before wiring.

UART0 is also the USB console: do not drive GPIO3 from the Pi while USB is attached.

ESP32 and Raspberry Pi are 3.3 V logic. The 6 V supply must share GND with both.

Sheet: / File: motor-controller.kicad_sch		
Title:		
Size: A3	Date:	**Rev:**
KiCad E.D.A. 10.0.6		Id: 1/1