



RMSE normalized to No-Gain (external all-data)

—■— No-Gain —●— Gain+SS=0.001 —▲— Gain+SS=0.01 —◆— Gain+SS=0.05


R5-11 | H₂S




R5-12 | H₂S



R5-11 | SO₂



R5-12 | SO₂



No-Gain = 1. Values below 1 indicate lower RMSE than No-Gain; no case averaging.