


Q:1 Draw the projection of point A when a point A is 40mm above h.p and 25mm in front of the V.P.

→ Given data,

Point A lies in first Quadrant

40 mm above h.p

25 mm in front of V.P




Q:2 Draw the projection point B when point B is 15 mm above h.p and 40 mm behind V.P.

→ Given Data,

Point B lies in 2nd Quadrant

point B lies 15mm above h.p

point B lies 40mm behind V.P




Q:3 Draw the projection of point C when the point C is 25 mm below h.p and 25 mm behind the V.P.

→ Given data,

Point C lies in 3rd Quadrant

Point C lies 25 mm below h.p

point C lies 25mm behind V.P




Q:4 Draw the projection of point D when point D is 40mm below the h.p and 30mm in front of V.P.

→ Given data,

Point D lies in 4th Quadrant

Point D lies 40mm below h.p

point D lies 30mm in front of V.P




Q:5 Draw the projection of point B when the point 12 mm above the H.P and lies on V.P.

→ Given data,

12 mm above h.p - point B

on V.P - point B




Q:6 Draw the projection of point C when the point is 22 mm in front of V.P and on H.P

→ Given data,

Point C is 22 mm in front of V.P

Point C is on H.P




Q:7 Draw the projection of point E which lies on H.P and 37 mm behind V.P.

→ Given data,

Point E lies on H.P

point E is 37mm behind V.P




Q:8 Draw the projection of point G which lies on V.P and 35 mm below H.P.

→ Given data,

Point G lies on V.P


Point G is 35mm below H.P



Q:9 Draw the projection of point I which lies on the both reference plane.

→ Given data,

Point I lies on the both reference plane (i.e. H.P & V.P)




Q:10 Draw the projection of Point M which is 35mm from h.p and 35mm from V.P and is in IInd quad.

→ Given data,

Point M is in IInd quadrant

∴ 35 mm above h.p

35 mm behind V.P



Q:11 Draw the projection of point N which is 15mm from V.P and 45mm from H.P and is in IInd quadrant.

→ Given data,


15 mm from V.P - point - N

45mm from H.P - point - N

Point N lies in IInd quadrant

∴ 15 mm in front of V.P

45mm below H.P.



Q:12 Draw the projection of point O which is 30 mm from both reference plane and is in IIIrd quadrant.


→ Given data,

Point O is 30mm from both reference plane.

Point O lies in IIIrd quadrant.

∴ point O is 30mm below h.p

point O is 30mm behind V.P




Q:13 Draw the projection of point P which is 25 mm from H.P and 45 mm from V.P and is in Ist quadrant

→ Given data,

Point P lies in Ist quadrant

∴ point P is 25mm above h.p

45mm in front of V.P.



GRAMIN TECH. & MANAG. CAMPUS VISNUPURI, NED

NAME: NABEEL AHMED AHMED MUBASSIR

TITLE: SHEET ON PROJECTION OF POINTS

CLASS: FY B-TECH (COMP. ENG. 6) Roll NO: 24C0867

DATE: 15-10-2024 SHEET NO: 03 SCALE

METHOD OF PROJECTION: SIGN: MARKS:


Q:1 Draw the projection of point A when a point A is 40mm above h.p and 25mm in front of the V.P.

→ Given data

Point A lies in first Quadrant

40 mm above h.p

25 mm in front of V.P




Q:2 Draw the projection point B when point B is 15 mm above h.p and 40 mm behind V.P.

→ Given Data,

Point B lies in 2nd Quadrant

point B lies 15 mm above h.p

point B lies 40 mm behind V.P




Q:3 Draw the projection of point C when the point C is 25 mm below h.p and 25 mm behind the V.P.

→ Given data,

Point C lies in 3rd Quadrant.

Point C lies 25 mm below h.p

point C lies 25 mm behind V.P




Q:4 Draw the projection of point D when point D is 40mm below the h.p and 30mm in front of V.P.

→ Given data,

Point D lies in 4th Quadrant

Point D lies 40mm below h.p


point D lies 30mm in front of V.P



Q:5) Draw the projection of point B when the point is 12 mm above the H.P. and lies on V.P.

→ Given data,


12 mm above h.p. - point B
on V.P. - point B



Q:6) Draw the projection of point C when the point is 22 mm in front of V.P. and on H.P.

→ Given data,


Point C is 22 mm in front of v.p.
Point C is on H.P.



Q:7) Draw the projection of point E which lies on H.P. and 37 mm behind V.P.

→ Given data,


Point E lies on H.P.
Point E is 37 mm behind V.P.



Q:8) Draw the projection of point G which lies on V.P. and 35 mm below H.P.

→ Given data,


Point G lies on V.P.
Point G is 35 mm below H.P.



Q:9) Draw the projection of point I which lies on the both reference plane.

→ Given data,

Point I lies on the both reference plane (i.e. H.P. & V.P.)




Q:10) Draw the projection of point M which is 35 mm from h.p. and 35 mm from v.p. and is in IInd quad.

→ Given data,

Point M is in IInd quadrant

∴ 35 mm above h.p.
35 mm behind v.p.



Q:11 Draw the projection of point N which is 15mm from V.P and 45mm from H.P and is in IV quadrant.

→ Given data,


15 mm from V.P - point - N

45 mm from H.P - point - N

Point N lies in IV quadrant.

∴ 15 mm in front of V.P

45 mm below H.P.



Q:12 Draw the projection of point O which is 30 mm from both reference plane and is in III quadrant.


→ Given data,

Point O is 30 mm from both reference plane.

Point O lies in III quadrant.

∴ point O is 30 mm below h.p &

point O is 30 mm behind V.P




Q:13 Draw the projection of point P which is 25 mm from H.P and 45 mm from V.P and is in I quadrant.

→ Given data,

Point P lies in I quadrant

∴ point P is 25 mm above h.p &

45 mm in front of V.P.



GRAMIN TECH. & MANAG. CAMPUS VISNUPURI, NED

NAME: NABEEL AHMED AHMED MUBASSIR

TITLE: SHEET ON PROJECTION OF POINTS

CLASS: FY B-TECH (COMP. ENG.) ROLL NO: 24C0B67

DATE: 15-10-2024 SHEET NO: 03 SCALE

METHOD OF PROJECTION:-

SIGN: .

MARKS: