
Same square area and perimeter at every eligible position
Bi=0.01
Bi=1
Bi=100
Square center x
Square center y
Total Q change from unperforated chamber (%)
0.0
0.2
0.4
0.6
0.8
1.0
7.5
5.0
2.5
0.0
−2.5
−5.0
−7.5