





VIEW A





VIEW B











NOTES



SET TO DIM SHOWN WITH AIR PRESSURE AT 80 PSI (FINAL ADJUSTMENT MAY BE REQ'D AT INSTALLATION ON INSERTION MACHINE).



ORIENT PIN WITH SLOT TO REAR AS SHOWN. PIN TO PROTRUDE . 100 TO RIDE IN SLOT IN CARRIER.



SET UP .010" GAP BETWEEN DOG (.062 X .230) AND HOUSING WHILE ON THE HIGHEST POINT OF RATCHET ASSEMBLY, WITH AIR PRESSURE SET AT 80 PSI. MARK TOOTH USED TO SET GAP.



SET UP .002" GAP BETWEEN DOG (.062 X .250) AND RATCHET ASSEMBLY WHILE IN THE SAME SET UP POSITION AS WAS USED IN NOTE 3. AIR PRESSURE SET AT 80 PSI.

TIME FOR EXTEND 70MS MAX (DRY CYCLE)
TIME FOR RETRACT 95MS MAX (DRY CYCLE)
DISP HEAD MUST CUT PAPER .004 THICK
DISP HEAD MUST CUT CARRIER TAPE .035 THICK



APPLY LOCTITE 222 NO. BLKM07389.



SMALLEST MEASURED CLEARANCE SHOULD BE .0015
BETWEEN THE CUTTER AND STANDARD CUTTER.
CLEARANCE SHOULD BE CHECKED THE FULL LENGTH
OF THE CUTTER (BOTTOM TO TOP). ENSURE BOTH CUTTER
SURFACES ARE ENGAGED AT THE POINT OF MEASUREMENT.



SET REFIRE FLUSH TO THE EDGE OF CUTTER HOLDER. REFIRE NOT TO OVERLAP MORE THAN .010".



LEAVE STRESS LOOP IN GROUND WIRE FROM REFIRE ASSEMBLY.



APPLY FILM OF ANDEROL 40833833 TO BUTTON AND COMPRESSION SPRING.



APPLY ANDEROL 40833833 TO ALL SLIDING SURFACES.



APPLY A LIGHT FILM OF ANDEROL 40833833 TO PIN OF CAM UNIT.



SET .001 GAP MAX BETWEEN HOUSING AND DRIVER BY TIGHTENING SSSFP SET SCREW. SET GAP WITH DRIVER STROKED OUT SO CUTTER AND STANDARD CUTTER ARE FLUSH.



BAG AND ATTACH 2.5MM UPPER PUSHER TO CYLINDER ASSEMBLY CABLE.



MANUFACTURING SET UP DIMENSIONS: 5.796 ±.005
APPLIES AT DRIVER FROM BOSS OF HOUSING OR
.656 ±.005 APPLIES AT DRIVER FROM FRONT SURFACE
OF HOUSING.



5.0 UPPER PUSHER SHOWN FOR 5.0 MM COMPONENTS. FOR 2.5 MM COMPONENTS REPLACE WITH 2.5 MM UPPER PUSHER.



INSTALL CURVED SPRING WASHER WITH CROWN UP (TOWARDS CHUTE).



INSTALL ID LABEL WITH PART NUMBER, REV, DATE AND SERIAL NUMBER THIS LOCATION.



CRITICAL TO FUNCTION.



NO GREASE AREA - WIPE OFF GREASE IN THIS AREA BEFORE ASSEMBLING THE FEED WHEEL ON TO THE RATCHET ASSEMBLY.

Page	12	Rev.	А	T50849901		RL	DISP	HD A	(SSY	
DET NO.	ITEN	M NO.		DE	SCRIPTI	ON			QTY	U/M
	1021	9003	BU	SHING, DU						ΕA
2	1024	9133	SP	RING, COMPRE	SSION					ΕA
3	2183	8000	ВЕ	ARING, BALL					2	ΕA
4	2523	9000	LO	CKING ELEME	NT					ΕA
5	3019	4200	CA	RRIER						ΕA
6	3019	4400	DR	IVER						ΕA
7	3020	0100	00	VER						ΕA
8	3048	6900	SP	RING						ΕA
9	3053	5803	PΙ	N						ΕA
10	3057	6403	ST	OP						ΕA
	3059	0701	RE	TAINER PIN,	SPRING					ΕA
12	3088	1501	PL	ATE, NUT						ΕA
13	3094	6901	PΙ	N, DRIVE						ΕA
4	3094	7001	CL	AMP PLATE						ΕA
15	4013	0305	НО	LDER, CUTTE	R					ΕA
16	4183	5802	H0	USING						ΕA
17	4272	7001	RA	TCHET ASM						ΕA
18	4362	0501	SP	RING, R TOR	SION					ΕA
19	4362	0601	SP	RING, R TOR	SION					ΕA
20	44 4	6102	СН	UTE						ΕA
21	4417	0501	DO	G						ΕA
22	4417	0502	DO	G						ΕA
23	4417	0701	CA	M UNIT						ΕA
24	4423	6802	FE	ED WHEEL						ΕA
25	4423	9301	GI	В						ΕA
26	4442	6401	DR	IVER						ΕA
27	4442	6606	PU	SHER, UPPER	5.0					ΕA
28	4442	6701	PU	SHER, LOWER						ΕA
29	4706	1704	CY	LINDER ASSY						ΕA
30	4873	2302	FL	AG, MOLDED						ΕA
			This	Document Supports	Assembly 50	8499	Ol Rev.			

Page	e 13 Rev.	A T50849901	RL DISP	HD ASSY	
3	49599001	CUTTER, STANDARD			ΕA
32	80000514	SHCS 10-32 X 3/8		2	ΕA
33	80000515	SHCS 10-32 X 1/2		5	ΕA
3 4	80000518	SHCS 10-32 X 7/8		3	ΕA
35	80004601	SSSFP 4-40 X 1/8			ΕA
36	80004602	SSSFP 4-40 X 3/16			ΕA
37	80004701	SSSFP 6-32 X 1/8			ΕA
38	80004911	SSSFP 10-32 X 3/8			ΕA
39	80005107	SSSFP 5/16-18 X I			ΕA
40	80008305	PHMS 2-56 X 3/8		2	ΕA
4	80009303	FHMS 2-56 X 1/4		2	ΕA
42	80010001	SDP 3/16 X 1/2		I	ΕA
43	80014103	SPRG PIN . 125 X . 437		I	ΕA
44	80014302	SPRG PIN .187 X .500		I	ΕA
45	800 43 2	SPRG PIN .187 X 1.250)		ΕA
46	80015103	HEX JAM NUT 5/16-18			ΕA
47	80017101	SFHS-NP 6-32 X 3/8		2	ΕA
48	80018705	SLW #10		2	ΕA
49	80018804	FW #8			ΕA
50	80018805	FW #10		2	ΕA
51	80019007	ITLW 5/16		I	ΕA
52	80024012	HHMS 10-32 X 5/8		3	ΕA
53	80062601	BHTSCS 6-32 X 1/2			ΕA
5 4	80067817	SHCS-ZP 1/2-20 X 1 3	3 / 4		ΕA
55	90055676	15mm DSP HD LINK			ΕA
56	BLKE01071	CLAMP,3/16"			ΕA
57	BLKM05004	BEARING, THRUST			ΕA
58	BLKM06312	RING, RETAINING			ΕA
59	BLKM06328	RET RING 5100-37			ΕA
60	BLKM06329	RET RING 5100-18		4	ΕA
6	BLKM06597	"NO-MAR" SET SCREW			ΕA

This Document Supports Assembly 50849901 Rev. -

Pag	e 14 Rev.	A T50849901 RL DISP HD AS	SY	
62	T	SPACER, SHAFT		ΕA
63	BLKM07112	WSHR, THR, NYL. 250ID. 5000D. 062W	4	ΕA
6 4	BLKM07137	CURVED SPRING WASHER		ΕA
6.5	BLKM07199	WAVE SPRING WASHER		ΕA
66	C65356004	BUTTON		ΕA
67	C65356014	CUTTER		ΕA
68	C65356019	ECCENTRIC		ΕA
6 9	C65356028	INSERT		ΕA
		USED BUT NOT SHOWN ITEMS		_
70	44426607	PUSHER, UPPER 2.5mm		ΕA
71	T50849901	RL DISP HD ASSY		ΕA