

Lab_lint_1.1

Objectives:-

- Run Lint on design files using SpyGlass tool and analyze all the violations and fix them.

Steps:-

1. Invoke Spyglass using GUI Mode
2. Read Design Files list
3. Modify Read Design Options if needed
4. Configure Goal Rules and Parameters
5. Run lint/lint_rtl
6. Analyze and debug the violation through the GUI
7. Fix or Waive the violations