



ZPTD_QC22 in Action

Your Guide to Certificate
of Analysis by Batch



HOW TO USE THIS GUIDE

This training guide is designed to support users with varying levels of experience in SAP.

Whether you are new to the system or an advanced user, the guide provides structured information to help you navigate and utilize the relevant SAP transaction effectively.

Here's how to make the most of this guide:

- **For Beginners:**
 - **Start with the Basics:** Begin with introductory sections that explain the purpose and functionality of the transaction, as well as navigation tips.
 - **Hands-On Practice:** Use practical examples and scenarios to apply your learning in a test environment.
 - **Focus on Troubleshooting:** Pay attention to the common mistakes and troubleshooting section to avoid typical errors and build confidence.
- **For Advanced Users:**
 - **Go Straight to Advanced Features:** Focus on sections that provide in-depth details about specific tools, data interpretation, and cross-functional integration.
 - **Efficiency Tips:** Leverage the best practices and tips section to refine workflows and improve system efficiency.
 - **Quick Reference:** Use transaction steps as a checklist or reference guide for navigating the system quickly and accurately.
- **General Tips for All Users:**
 - **Use the Guide Modularly:** The guide is structured to allow you to skip sections or dive deeper into specific topics based on your learning needs.
 - **Leverage Tools and Features:** Familiarize yourself with tools like search filters, linked documents, and logs to maximize your productivity.
 - **Integrate Knowledge Across Modules:** Explore how the transaction integrates with other SAP modules for end-to-end process visibility.
 - **Focus on Outcomes:** Regularly refer to the expected outcomes section to ensure you are achieving the intended objectives.

This guide is flexible and provides both foundational knowledge and advanced insights, making it useful for a wide range of SAP users and business scenarios.

TABLE OF CONTENTS



1. [Audience](#)



2. [Objective / Purpose](#)



3. [Prerequisites](#)



4. [Introduction to the ZPTD_QC22 Transaction](#)



5. [Navigating the ZPTD_QC22 Screen](#)



6. [Understanding Certificate of Analysis by Batch](#)



7. [ZPTD_QC22 Process Flow](#)



8. [Practical Scenarios in ZPTD_QC22](#)



9. [ZPTD_QC22 Tools and Features](#)



10. [Best Practices and Tips for Using ZPTD_QC22](#)



11. [Transaction Steps](#)



12. [Expected Outcome](#)



13. [Common Mistakes and Troubleshooting](#)



14. [Conclusion](#)



15. [Revision History](#)



16. [Document Information](#)



1. Audience

This guide is designed for:

- Quality Assurance / Quality Control (QA / QC) personnel in chemical manufacturing.
- Laboratory technicians.
- Production supervisors.
- SAP users involved in batch release and documentation.
- Personnel responsible for generating and distributing Certificates of Analysis (CoAs).
- Anyone who needs to understand how to use the ZPTD_QC22 transaction.



2. Objective / Purpose

By the end of this training, participants should be able to learn how to effectively use the ZPTD_QC22 (**Certificate of Analysis by Batch**) transaction in SAP.

- **Objective:**

The objective of this training is to enable users to:

- Gain a thorough understanding of the ZPTD_QC22 transaction.
- Effectively navigate the ZPTD_QC22 screen and its various elements.
- Generate accurate and timely Certificates of Analysis (CoAs).
- Utilize the transaction's features to meet quality documentation requirements.
- Troubleshoot common issues and apply best practices.

- **Purpose:**

The purpose of the ZPTD_QC22 transaction is to:

- Provide a user-friendly interface for creating Certificates of Analysis (CoAs) for batches of chemical products.
- Streamline the process of quality documentation.
- Ensure that customers receive accurate and complete information about product quality.
- Support compliance with regulatory requirements and industry standards.
- Facilitate efficient batch release and shipment.
- Improve data accuracy and reduce manual errors in CoA generation.



3. Prerequisites

To benefit from this guide, users should have:

- Basic knowledge of SAP navigation.
- Familiarity with quality management processes in chemical manufacturing.
- Understanding of batch management and quality inspection concepts.
- Knowledge of Certificate of Analysis (CoA) content and purpose.
- Appropriate SAP authorization to access and execute the ZPTD_QC22 transaction.
- Familiarity with the master data relevant to quality management, such as:
 - Material master data
 - Batch master data
 - Inspection plans
 - Certificate profiles
 - Quality results



4. Introduction to the ZPTD_QC22 Transaction

Overview of ZPTD_QC22 in SAP

ZPTD_QC22 is a custom transaction (Z transaction) in SAP that is specifically designed for generating **Certificates of Analysis (CoAs) for Batches**, in Solenis. Standard SAP provides QC22, but ZPTD_QC22 is a customized version. It allows users to retrieve quality inspection results and compile them into a standardized document that certifies the quality of a specific batch of material. It offers enhancements or modifications to the standard QC22 transaction to meet specific business needs.

Importance in Chemical Manufacturing:

ZPTD_QC22 is particularly important in chemical manufacturing because:

- **Quality Assurance:** CoAs are critical for verifying that chemical products meet stringent quality specifications.
- **Regulatory Compliance:** The chemical industry is heavily regulated, and CoAs are often required to demonstrate compliance with standards (e.g., ISO, REACH).
- **Customer Requirements:** Customers rely on CoAs to assess the quality and suitability of chemical products for their applications.
- **Traceability:** CoAs provide a record of the quality of a specific batch, enabling traceability throughout the supply chain.
- **Batch Release:** CoAs are often a prerequisite for releasing a batch for shipment to customers.
- **Product Liability:** In case of quality issues, CoAs serve as important documentation.



5. Navigating the ZPTD_QC22 Screen

1. Accessing ZPTD_QC22:

There are two primary ways to access the ZPTD_QC22 transaction:

- a. **Transaction Code:** In the SAP Easy Access screen, enter "ZPTD_QC22" in the transaction code field and press Enter.
- b. **SAP Menu:** Navigate through the SAP menu to the appropriate path (e.g., Quality Management > Quality Certificates > ZPTD_QC22).

2. Key Screen Elements & Selection Screen Overview:

The ZPTD_QC22 transaction typically consists of a selection screen and an output screen.

a. Selection Screen:

This screen allows you to specify the criteria for selecting the batch for which you want to generate a CoA. Key elements include:

- i. **Material:** The material number of the chemical product.
- ii. **Plant:** The plant where the material was produced.
- iii. **Batch:** The specific batch number for which the CoA is required.
- iv. **Inspection Lot:** The inspection lot number associated with the batch.
- v. **Customer:** The customer who will receive the material. This will influence the CoA format or content.
- vi. **Certificate Profile:** The certificate profile determines the layout and content of the CoA.
- vii. **Output Type:** Options for displaying or printing the CoA (e.g., screen, printer, PDF).
- viii. **Date Range:** To select batches created within a specific date range.

b. Selection Screen Overview:

- i. The selection screen is crucial for filtering the data and retrieving the correct information for the CoA.
- ii. Carefully enter the selection criteria to ensure that the generated CoA is for the intended batch.
- iii. Default values may be pre-populated in some fields.
- iv. Help fields (F1) are available for most fields to provide more information.

3. Customizing the Display & Output Screen Overview:

a. Output Screen:

This screen displays the generated Certificate of Analysis.

It includes:

- i. **Header Information:** Material, batch number, date of manufacture, customer, etc.
- ii. **Inspection Characteristics:** A list of quality characteristics that were tested.
- iii. **Specifications:** The acceptable range or limits for each characteristic.
- iv. **Results:** The actual measured values for each characteristic.
- v. **Overall Evaluation:** A summary of the batch quality (e.g., "Meets Specifications," "Released").
- vi. **Signature:** Electronic or physical signature of the person responsible for quality control.
- vii. **Custom Fields:** Any additional fields that are specific to Solenis.

b. Customizing the Display:

- i. ZPTD_QC22, being a custom transaction, offers some customization options. These include:
 - **Layout Selection:**
Choosing from different CoA templates or layouts.
 - **Field Selection:**
Specifying which fields to include or exclude from the CoA.
 - **Sorting and Grouping:**
Arranging the data in a specific order.
 - **Output Format:**
Selecting the output format (e.g., PDF, print, Excel).

ii. Standard SAP features for output customization are also available, such as:

- **Print parameters.**
- **SAPScript / SmartForms.**
- **ALV (ABAP List Viewer).**




6. Understanding Certificate of Analysis by Batch

A Certificate of Analysis (CoA) is a document that provides detailed information about the quality of a specific batch of material. For ZPTD_QC22, the CoA will typically include:


- **Batch Identification:** Material number, batch number, and other identifying information.
- **Inspection Results:** The results of quality tests performed on the batch, including the measured values for each quality characteristic.
- **Specifications:** The acceptable limits or ranges for each quality characteristic, as defined in the material specification or inspection plan.
- **Test Methods:** The methods used to perform the quality tests.
- **Manufacturing Information:** Date of manufacture, production location, and other relevant manufacturing details.
- **Customer Information:** The name and address of the customer (if applicable).
- **Storage and Handling:** Any special storage or handling requirements for the material.
- **Declaration of Conformity:** A statement that the batch meets the specified quality requirements.
- **Approval:** Signature and date of the person responsible for quality control.

The CoA is a critical document that:

- Verifies product quality.
- Provides assurance to the customer.
- Supports regulatory compliance.
- Facilitates batch release.



7. ZPTD_QC22 Process Flow





8. Practical Scenarios in ZPTD_QC22



Batch Release: After a batch of chemical product has passed all quality inspections, ZPTD_QC22 is used to generate the CoA, which is required before the batch can be released for shipment.



Customer Request: A customer requests a CoA for a specific batch of material that they have received or are about to receive.



Quality Audit: During a quality audit, the auditor requests CoAs for selected batches to verify compliance with quality standards.



Complaint Investigation: If a customer complains about a quality issue, the CoA for the affected batch is retrieved from SAP to investigate the problem.



Regulatory Reporting: CoAs may be required for regulatory reporting purposes.



Internal Documentation: CoAs are generated and stored for internal quality control records.



Sample Shipment: When sending a sample to a customer, a preliminary CoA may be generated.



9. ZPTD_QC22 Tools and Features


ZPTD_QC22 includes the following tools and features:

- **Selection Variants:** Saving frequently used selection criteria for quick access.
- **Output Options:** Printing, saving as PDF, sending electronically (e.g., via email).
- **Preview:** Viewing the CoA on the screen before printing.
- **Customization:** Options to customize the layout and content of the CoA.
- **Error Handling:** Messages to inform the user of any issues (e.g., missing data, authorization problems).
- **Help Function:** Accessing online help documentation for the transaction.



10. Best Practices and Tips for Using ZPTD_QC22

- **Accuracy:** Ensure that all selection criteria are entered correctly to generate the CoA for the correct batch.
- **Timeliness:** Generate CoAs in a timely manner to avoid delays in batch release and shipment.
- **Completeness:** Verify that the CoA contains all the required information.
- **Consistency:** Use consistent settings and formats to ensure that CoAs are uniform.
- **Authorization:** Ensure that only authorized personnel can access and use ZPTD_QC22.
- **Training:** Provide adequate training to all users of ZPTD_QC22.
- **Documentation:** Document the process for generating and distributing CoAs.
- **Regular Review:** Review the CoA format and content periodically to ensure that it meets current requirements.
- **Data Integrity:** Ensure that the underlying quality data (inspection results) is accurate and reliable.
- **System Maintenance:** Work with the IT department to ensure that ZPTD_QC22 is properly maintained and updated.
- **Use Selection Variants:** Save frequently used selection criteria to save time.
- **Verify Output:** Always preview the CoA before printing or sending it.



11. Transaction Steps

1. **Access ZPTD_QC22:**
Enter "ZPTD_QC22" in the transaction code field and press Enter.



2. Enter Material
Note: This transaction will not work for child materials set up for material determination

3. Enter Batch

Quality Certificate for Batch

Batch selection	
Material	430090
Batch	2W611371

4. Click [Choose Recipient]
 - a. Optional to enter a customer account number

Data regarding the recipient	
Choose recipient	

- b. If a customer account is entered, customer specs will be applied if maintained

Recipient	
☒ Customer number ☐ Customer contact person ☐ Vendor number ☐ User-Definable Address ☐ No recipient	
☒ ☐	

- c. Choose No Recipient if no customer account is available

Data regarding the recipient	
Customer number	EN
Language	EN
☒ Customer ☐ Choose recipient	

Data regarding the recipient

Choose recipient

Recipient

☐ Customer number
☐ Customer contact person
☐ Vendor number
☐ User-Definable Address
☒ No recipient

✓ ✗

5. Enter Plant
6. Click Processing in Foreground

Control data for processing

Other profile

Sending plant: 4701

Archiving mode: Print only

Transmission medium: Print output

☒ Processing in foreground

☐ Profile determination log

Profile determ. key date: 17.08.2016

7. Click execute
8. A pop-up with messages may be displayed
 - a. If all messages have a green light, click continue (green check)
 - b. If any message is red, this indicates a problem and the transaction has failed
 - i. Message "The data for batch xxx cannot be found" indicates that no results were found to generate the COA
 - ii. Message "No certificate profile was found" indicates missing master data, email the QM master data group to resolve the problem
9. In the Print pop-up, click [Print Preview] or [Print]

Storage Mode: Print only

Print Preview Print Ad

Print Preview of nan2 Page 00001 of 00001

Print Preview of nan2 Page 00001 of 00001



Page 1 of 1

Certificate of Analysis

Customer Order:		Ordered Quantity: 0.000	
Shipped From: TW NANTOU PLANT		Order Number:	
Delivery:		Date Shipped:	
Sold To Number:		PRESSTIGE FP7013 IBC 1000L	
Presstige(TM) FP7013 Felt Cleaning And Conditioning Agent			
Solenis Material Number: 430090			
Characteristics	Unit	Specification	Batch
			2W611371



12. Expected Outcome

By following this guide to complete the ZPTD_QC22 process, you should be able to:

- Correctly generate a Certificate of Analysis for the selected batch.
- Accurately and completely document batch quality.
- Streamline the CoA generation process to make it efficient.
- Improve customer satisfaction through timely provision of quality information.
- Comply with regulatory requirements.
- Reduce manual effort and errors.



13. Common Mistakes and Troubleshooting

1. Mistake: Incorrect CoA Generated

Cause: Entering incorrect selection criteria (e.g., wrong batch number).

Solution: Double-check all selection criteria before executing the transaction.

2. Mistake: No CoA Found

Cause: No inspection results recorded for the batch.

Solution: Verify that quality inspections have been completed and results have been recorded. Check the inspection lot status.

3. Mistake: Missing Data on CoA

Cause: Required data (e.g., specifications, test methods) not maintained in the system.

Solution: Ensure that all necessary master data (material master, inspection plan, certificate profile) is complete and accurate.

4. Mistake: Error Message

Cause: System error.

Solution: Note the error message and consult the SAP help documentation or contact the SAP support team.

5. Mistake: Authorization Error

Cause: User does not have the required authorization to access ZPTD_QC22.

Solution: Contact the SAP security administrator to request the necessary authorization.

6. Mistake: CoA Layout Issues

Cause: CoA layout is not correct.

Solution: Check the assigned certificate profile and its configuration.

7. Mistake: Performance Issues

Cause: Transaction is running slowly.

Solution: Check system performance and network connectivity.



14. Conclusion

This comprehensive guide provides an overview of the SAP ZPTD_QC22 transaction which is a valuable tool for generating Certificates of Analysis in chemical manufacturing. By following this training guide and adhering to best practices, users can effectively utilize the transaction to ensure accurate quality documentation, meet customer requirements, and support regulatory compliance. Proper use of ZPTD_QC22 contributes to efficient batch release, improved data integrity, and enhanced quality assurance.



15. Revision History

Version	Date	Author	Approved By	Description
1.0	26-Apr-25	Aparna Bhambure	Kathryn McKenning	Base Document



16. Document Information

- **SAP Module:** Quality Management (QM)
- **Transaction Code:** ZPTD_QC22 – Certificate of Analysis by Batch
- **Process:** Production to Distribution (PTD)
- **Version:** 1.0
- **Date:** 26-Apr-25
- **Author:** Aparna Bhambure