

# Important point of drawing

TA Satoru Hattori Yasuyuki Oda

# About drawings column



The important points of drawing column are following:

- The format of drawing unify to based on JIS format
- The unit of length unify to the metric system (millimeter)
- A full name should written in column of plotter
- The part name should written in column of product name
- The issue number should written in column of figure number
- Do not written in drawing column by handwriting

If you don't determine material, this column should blank



### About dimension lines




- The dimension lines unify to based on JIS format
- The dimensions should be placement at center
- The arrows should not pile to the hatching
- The space between dimension lines should be at equal intervals
- The color of dimension line should written in black


Example 37 37

# Bad examples







- The detail drawing is too large
- The dimension lines have parenthesis



- Dimension lines should not be colored
- Spell miss (TERU⇒THRU)



The dimensions pile to drawing column




The submit format should be PDF

#### **Good example**

\*Personal name and Student ID number is hidden





- ※"断面図" is "cross section", "詳細図" is "detail drawing".
- XThis form have a little matter. It will open 27 holes of φ6mm.



# Precautions

- Draw following basic referring to a textbook (drawing examples) of the drafting.
  - Review the kind of the line, the placement of the figure, how to write dimensions, etc.
- drawing maps have to be able to tell what you want to make to processor.
  - submit after you checked whether it is easy to see and demensions are all written.


## Editing method of the drawing column



1 Create new drawing




2 In this class, choose A(ANSI) horizontal as the sheet format.



### Editing method of the drawing column




3 The drawing sheet should be as following.



4 right-click on the drawing sheet.

→edit sheet format



XIn JIS drawing column is like this

計示 <i>なが</i> 場合: 計法体型 <i>以一</i> タとする 更 <b>国 和</b> さ:		仕上げ:	性上げ:					四面测定不可	কয়	
公差 : 寸法 : 角度 :										
	名 前	景名	日付				有称:			
製鋼										
検回										
集器										
無産										
品管				材料:		四面条号		Draw	,7	A.
								Draw	/	, ,,
		##:					尺度:1:1	w s	k1 / 1	






5 drawing column get blue and get able to be edited (double-click text and can edit, move of line etc are also available



can add text at "annotation tool bar -notes"



\*Can write & add lines at" sketch"
(ex when you wanna increase or divide the list)





## At last

If you have a questions ,don't hesitate to ask us

Asai • Numata/Nagai labolatory Room 405 of Mechanical building No.1

#### 服部 悟 (Hattori Satoru)

hattori.satoru@aero.mech.tohoku.ac.jp

#### 小田 泰之 (Oda Yasuyuki)

oda.yasuyuki@aero.mech.tohoku.ac.jp