

DEVIATION FROM TRUE & SQUARE  $\frac{1}{8}$ " [±3.2mm] IN 50 FEET [15.2m]

DO NOT SCALE - IF IN DOUBT ASK

BREAK ALL SHARP CORNERS AND EDGES - REMOVE BURRS REFER TO STD WELDING DWG D-27317 FOR WELDING DIRECTIONS

CAN-ENG Internal Information: Drawing State: Approved ,Drawing Version: 11 Model Filename: C:\DOCMAN\Jobs\112994\LOT 030\SolidWorks Models\112994-030-46-01 ,Model State: Approved,Model Version: 14

HEARTH ELEVATION  $\pm \frac{1}{32}$ " [0.8mm]

ANGULAR  $\pm \frac{1}{2}$ °