## SERVICE REPORT WORK ORDER NO. WORK ORDER TYPE INCIDENT TYPE PHL01943 Aftersales Aftersales-PM500



PHL01943	Aftersales	Aftersales-PM500			MATERIAL HANDEING			
CUSTOMER NAME	CUSTOMER NAME		CUSTOMER ADDRESS					
ARCHON NELL INCORPORATED		,,,TAGUIG CITY						
DEPARTMENT	CONTACT PERSON	CONTACT NO.	EMAIL ADDRESS	Invoice NO	DR NO	Quote NO /MRI NO		
Contract Status	FLEET NO.	BRAND	MODEL	SERIAL NO.	PRODUCTION YEAR	HOUR METER		
Afeter sales		TOYOTA	62-8FD30	33746				
ENGINE (IC)	DRIVE MOTOR(EL)	LIFT MOTOR(EL)	TRANSMISSION	MAST TYPE	MAST HEIGHT	ATTACHMENT		
	The state of the s							

**REQUESTED SERVICE** 

CUSTOMER REQUEST CUSTOMER REQUEST								
FUNCTION							ERROR CODE	
() CRANK (IC)	()POWER(E	L)	()TRAVEL (F/R)		()STEER (L/R)	()LIFT (U/D)	()TILT (F/R)	
DATE & TIME RECEIVED		SITUATION	I	REÇ	UEST RECEIVED BY		OTHER REMARKS	

RENDERED SERVICE

DATE & TIME STARTED	SITUATION BEFORE	PROBLEM	
LABOR NO.		QTY	
	•		J.
PART NO.		QTY	
			·
DATE 9 TIME FINICHED	DATE & TIME FINISHED CITHATION AFTED TECHNICIAN DEMA		

DATE & TIME FINISHED	SITUATION AFTER	TECHNICIAN REMARKS
11/8/2022 10:15:00 AM		

**RECOMMENDED SERVICE** 

LABOR NO.	LABOR DESCRIPTION	QTY	
		···	
PART NO.	PART DESCRIPTION	QTY	

I HEREBY CERTIFY THAT THE ABOVE SERVICES HAVE BEEN CARRIED OUT TO MY ENTIRE SATISFACTION AND

TECHNICIAN NAME & SIGNATURE	CUSTOMER NAME & SIGNATURE	CUSTOMER REMARKS
		REPLACED PARTS

## HANDLING INNOVATION INCORPORATED

(02) 7500-1584, (02) 7577-8329, (0917) 834-2402, (0917) 821-

7578, (0998) 840-0619, (0998) 840-0620, (0925) 712-0338, (0933) 829-0020