SYNTHETIC TEST DOCUMENT — NOT A REAL RECORD

# Synthetic Second Repair Job Sheet

All names, addresses, amounts, events, references and communications below are invented solely for software testing. No logo or official branding is used.

## Service provider

North Loop Device Lab (fictional independent workshop)
7 Invented Service Lane, Fictional Nagar, Chennai 600000
No manufacturer or authorized-service affiliation is claimed.

## Job details

Job reference: SIM-JOB-250318-B
Case reference: SIM-CASE-2601
Service date: 18 March 2025
Customer: Mira Sen
Product/model: Sony WHM1000X wireless headphones / WHM1000X
Prior related job: SIM-JOB-250203-A

## Reported fault

Same reported fault: headphones unexpectedly power off after approximately two minutes of playback.

## Inspection and different fictional work

Technician recorded battery voltage sag under simulated load and cleaned the charging-port contacts. A fictional battery pack was replaced with a test component; a 30-minute playback check completed without shutdown.

## Recorded outcome and subsequent report

Returned to customer on 18 March 2025. Customer subsequently reported recurrence on 22 March 2025: the headphones again powered off after approximately two minutes of playback. The recurrence is a customer report, not an independently verified finding.