# Week 5 Progress Report

George Bange ENE221-0109/2017

## **Tasks Completed**

- <u>Issue #140</u>: Review LoRa Module connections
- SD card module connection
- Fabrication of new PCB
- Visited PAUSTI

## **ESP32** pinout

Studied the ESP32-S GPIOs and their common applications

Some pins can't be used as digital output pins, these pins are 6,7,8,9,10,11,34,35,36 and 39

All GPIOs can be used as hardware interrupt pins


#### ESP32-S has:

- i. 18 ADC interfaces
- ii. 4 SPI interfaces
- iii. 3 UART interfaces (only UART 0 and UART 1 are available for use)
- iv. 2 I2C interfaces
- v. 2 DAC interfaces
- vi. 16 PMW interfaces
- vii. 2 I2S interfaces
- viii. 10 capacitive sensing GPIOs


#### LoRa module connection

HSPI (SPI2) configuration used

MOSI -> 13, MISO -> 12, CLK -> 14, CS -> 15



#### LORA MODULE




**NODE MCU** 


#### SD card module connection

VSPI (SP12) configuration used

MOSI -> 23, MISO -> 19, CLK -> 18, CS -> 5




#### SD CARD MODULE



### **Fabrication of new PCB**

We fabricated a double-sided PCB at Gear Box.

The PCB had a lot of continuity issues. Some are yet to be resolved



### **Visited PAUSTI**

We visited PAUSTI to find out what antenna testing equipment they have

The Electronics Lab has 2 VNAs and a Spectral analyzer which we will use to fabricate our antenna

They also have PCB fabrication equipment of upto 8 layers