

Pyramids QC Final Inspection Standard

#### 最終檢驗規範

客 戶: GCX

版本	變更日期	變更內容	變更者	審核
A1	2014/7/17	第一版	Bruce	
A2	2017/12/22	新增客訴紀錄	PHILIP	



Pyramids QC Final Inspection Standard

版本: A2 PART NAME PART NO. PYR Smart Sub for FWM-0001-01B FWM-0001-98 品 名 品 號 COLOR NONE 顏 色

略圖 Illustration:





#### 外觀/功能/組裝規範:

檢驗項目	檢驗工具	檢驗規範		
1	目視	FWM0001M2A依照啟鑫五金檢驗規範檢驗。	無	
2	目視	FWM0001M1B依照啟鑫五金檢驗規範檢驗。	無	
3	目視	FWM0001P2A、FWM0001P3A依照啟鑫塑膠檢驗規範檢驗。	無	
4	目視	FWM0001S3A依照啟鑫五金檢驗規範檢驗。	無	
5	目視	FWM0001P6A、FWM0001P1A依照啟鑫塑膠檢驗規範檢驗。	無	
6	目視	FWM0001P4A與FWM0001P5A於置中位置。FST-0024-77 x2pcs調整凸出0.16"~0.18"	附件一	
零附件:				
1	目視	零件包FWM-0001-98 BAG02內有:FWM0001M1B x1pcs、FST-0013-17(yN) x2pcs	附件二	
2	目視	零件包FWM-0001-98 BAG03內有:FWM0001P2A x1pcs、FWM0001P3A x1pcs、FST-0006-08(bN)	附件二	
3	目視	零件包FWM-0001-98 BAG04內有:FWM0001S3A x1pcs、FST-0013-11(yN) x2pcs	附件三	
4	目視	零件包FWM-0001-98 BAG05內有:FWM0001P6A x4pcs、FWM0001P1A x6pcs、FST-0007-04 x3pcs	附件三	

包裝方式:將FWM-0001-98 BAG00放入P-FWM-0001-98--642458176B並放上P-FWM-0001-98--636455D。最後封箱並貼上產品標籤與 透明PO,並且秤重並且記錄於過磅單上。












版本: A2

## 啟鑫科技/希馬頓科技 最終檢驗規範

Pyramids QC Final Inspection Standard

附件一







Pyramids QC Final Inspection Standard 版本: A2 附件二 FST-0013-17(yN) x2pcs FWM0001M1B x1pcs FWM-0001-98 BAG02 FWM0001P2A x1pcs FST-0006-08(bN) x2pcs FWM-0001-98 BAG03 FWM0001P3A x1pcs



版本: A2

## 啟鑫科技/希馬頓科技 最終檢驗規範

Pyramids QC Final Inspection Standard

附件三



8-32 X 1/4 FHMS 100 DEG (3PCS)

FWM0001P1A

VHC CHANNEL GUIDE BAR (6PCS

FWM0001P6A

VHC CABLE TIE BLACK (4PCS)

FWM-0001-98 BAG05



Pyramids QC Final Inspection Standard

#### 客訴問題記錄

NCMR#	10/10/2017 Norma159 diameter is not thru on spring mount (FWM0001M!B) in				
60506	this sub kit. This issue was found on two units from this lot. Material will be used				
00300					
	as is as this does no affect the fit, form function of the end product however vendor				
	will be notified of this issue. 10-32 depth meets drawing specification 零件FWM0001M1B漏做10-32螺牙. 2PCS				