

啟鑫科技/希馬頓科技 最終檢驗規範

Pyramids QC Final Inspection Standard

最終檢驗規範

客 戶: GCX

版本	變更日期	變更內容	變更者	審核
A1	2016/11/25	第一版	Richard	
A2	2017/6/21	增加客訴紀錄	PHILIP	
A3	2018/1/23	修正數字版品號	Richard	



啟鑫科技/希馬頓科技 最終檢驗規範

版本·A3	PYRAMIDS Pyramids QC Fina	I Inspection Stand	ard	
PART NAME	WC 0005 90/91 Front End Cub accombly	PART NO.	WS-0005-96	
品 名	WS-0005-80/-81 Front End Sub-assembly	品 號	W S-0003-90	
COLOR	BLACK OXIDE			
新 在	DLACK UAIDE			

略圖 Illustration:





檢驗規範

外觀/功能/組裝規範:

檢驗工具

檢驗項目

1	目視	外觀不可有破損和缺料	無
零附件:			
1	目視	WS-0005-96 BAG01內有WS0005T7A、LBL-0003-65、FST-0031-17 各為1PCS	附件一
		内盒A / P-WS-0005-96-2123630A中有WS0005T6A X 1PCS	

包裝方式:內盒B/P-WS-0005-96-2734255A包入內盒A/P-WS-0005-96-2123630A中有WS0005T6AX1PCS與WS-0005-96BAG01,貼上 成品標籤與PO和封口,放入外箱P-WS-0005-96-288285293B,一箱20入,在箱外貼上產品標籤和PO標籤,封箱後進行秤重的動作,並將數 據紀錄於成品過磅單









照片



版本: A3

啟鑫科技/希馬頓科技 最終檢驗規範

Pyramids QC Final Inspection Standard

附件一





啟鑫科技/希馬頓科技 最終檢驗規範

Pyramids QC Final Inspection Standard

客訴問題記錄

NCMR #58094	5/25/2017 Eason - Assy guys sees the rusty marks on WS0005T6_2 during assembly of both WOs (WO# 354171 & 358253). And issues were almost in the same					
	location. See the attached pictures.					
	零件WS0005T6A內螺紋孔生鏽問題					
1						