

Pyramids QC Final Inspection Standard

#### 最終檢驗規範

客 戶: GCX

品 號: FLP-0001-53B 品名: Sliding Vesa With Independent Tilt

版本	變更日期	變更內容	變更者	審核
A6	2020/8/4	增加LBL-0001-24 黏貼位置及增加客訴資訊	ANGELA	
A7	2020/12/24	設變,原FLP0001S9B變更為C版	ANGELA	
A8	2021/3/18	變更外箱照片及入箱方式的照片	ANGELA	
A4	2019/2/21	依客戶文件FLP-0001-53-WI rev C 增加FST- 0012-15 鎖至35 in-lbs	ANGELA	
A5	2019/12/20	設變,DU-FLP-0002-17 rev D 變更日期	ANGELA	



版本·A8	PYRAMIDS Pyramids QC Fina	i inspection Stand	ard	
PART NAME	Cliding Voca With Indopendent Tilt	PART NO.	FLP-0001-53B	
品 名	Sliding Vesa With Independent Tilt	品 號	TEI -0001-33B	
COLOR		Olean Amedine		
袹 伍	Clear Anodize			

略圖 Illustration:



#### 小鲷/小处/归壯归笳.

檢驗項目	檢驗工具	檢驗規範	照片
1	目視	檢查外觀有無污損、碰傷	1-1
2	目視	確認(KP0003P6A) x 4pcs及(FST-0031-51) x 2pcs,其組裝位置及順序正確無誤確認(WS0001P3A)內,有敲入(FST-0028-72) x 1pcs	1-2
		確認(WS0001P3A) x 1pcs及(HDW-0001-06) x 1pcs,組裝位置正確	
3	扭力扳手	檢查(FST-0015-65) x 2pcs是否鎖至20in-lb,(FST-0019-01B(YN)) x 2pcs 是否鎖至 150in-lb,(FST-0012-15(yN)) x 2pcs 是否鎖至35in-lb	1-3
4	目視	檢查是否於指定位置黏貼(LBL-0001-24)	1-4
§附件:			

|檢查零件包內是否含有:(FLP-0002-99 BAG01) x 1pcs ((FST-0052-35(bN)) x 4pcs、

(FLP-0002-99 BAG02) x 1pcs((FST-0052-43P(bN)) x 4pcs \( (FST-0052-45P(bN)) \) x

((HDW-0011-41) x 4pcs \( (HDW-0011-48) x 4pcs \( \) (FLP-0002-99 BAG04) x

## 包裝方式:

1

目視

將組裝完成的(FLP-0001-53B SUB)放入PE袋(P-0007-20--160700001H)中,再將(FLP-0002-17C BAG00)放入內盒(P-0002-R147--15241524127A)中,再放入成品(FLP-0001-53B SUB),封箱後,於箱上貼上產品標籤,20入/箱,外箱(P-FLP-0001-53B-625161669B) 封箱,於側邊上方貼上產品標籤,下方貼上透明PO。

 $(FST-0052-39(bN)) \times 4pcs \cdot (FST-0052-60P(bN)) \times 4pcs) \cdot$ 

4pcs \(\text{(FST-0052-47P(bN))}\) x 4pcs) \(\text{(FLP-0002-99 BAG03)}\) x 1pcs

1pcs((FST-0052-30(bN)) x 4pcs \( (FST-0052-59P(bN)) x 4pcs \) \

(DU-FLP-0002-17 Rev D) x 1pcs \( \text{(FLP0001S9C)} \) x 1pcs















附件二







Pyramids QC Final Inspection Standard





Pyramids QC Final Inspection Standard

### 客訴問題記錄

NCMR#	Notes: 07/31/2020 Luis D. Missing label. Parts are missing LBL-0001-24 (Country of				
118507	origin with date code label). Per routing and WI this label should be present on this				
	assembly.				
	LBL-0001-24A				