TRIMS	SRINIVASA ENTERPRISES			FormatNo. SRINIVASA/PRD/D01
				Issue Date:01.02.2019
	LIST OF ROOTCAUSE DETAILS			Rev.No.00
				Rev Date:
SL.No.	Break Down Name	Rootcause Name	Details	Status
2	Grinder Belt Cut	Self Life Experied	Experied	Inactive
3	Printer Shorted	Rain water sprayed in plugs	careless mistake	Active
4	Motor Burned	Over loaded operation	careless mistake	Inactive