

# **HLL Temporary Limitations Notice**


TO:	ALL PILOTS	DATE:	28 April 2023
TLN NUMBER:	002 - 2023		
SUBJECT:	: Hamilton Platform with Irish Sea Pioneer alongside		

#### 1. Comments

The Hamilton platform will have the Irish Sea Pioneer located alongside for approximately 6 weeks. The rig will be positioned immediately alongside the Hamilton Platform and may be bridge-linked.

The Hamilton Platform helideck is therefore closed, and all flights will route to the Irish Sea Pioneer

### 2. Photo/Dwg



HCA-FRM-09 Rev 01 February 2023



## HLL Temporary Limitations Notice

### 3. Existing HLL limitations

### Hamilton

Wind (T°)	Kts	Limitation / Comment	Non-Compliances
		Not available for flying operations	

### Irish Sea Pioneer

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		Jack Up (MODU)  Table 1(T) if overflight of 5:1 items is unavoidable  Approved friction surface – no net  No helicopter operations whilst on the move due to noncompliant HMS  Approved for AW169 operations	210° 150° 5:1 Misc	Outer edge of perimeter net frame 290mm Inboard foam monitor at 250mm adl. Foam pipe marginal infringement for AW169 ops. Forward access perimeter netting and lifeboat stations (port and stbd) infringe sector. HMS Rev.9B not fitted.

These restrictions/changes shall	
remain in force until (unless	Until further notice
previously revoked or suspended)	

Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect

HCA-FRM-09 Rev 01 February 2023