

HLL Temporary Limitations Notice

TO:	ALL PILOTS	DATE:	08 June 2022
TLN NUMBER:	11-2022		
SUBJECT:	Munro Helideck Refurbishment		

1. Comments

Harbour Energy are carrying out refurbishment of the Munro helideck. The work scope will include removal of top-coat of surface paint, followed by repaint of the helideck markings. The helideck net may be removed whilst work is in progress. Although it is not thought likely that the friction surface will be affected, the helideck will retain its 30kt wind restriction until such time as a friction test has been completed, therefore no further restrictions are required.

All crews should check with Harbour Energy on the status and condition of the helideck prior to any flights.

2. Photo/Dwg



3. Existing HLL limitations

Wind (T°)	Kts	Limitation /Comment	Non-Compliances
	30	NUI – 360-degree OFS deck • Daylight operations only – Aiming circle & "H" lights not fitted • No helicopter operations – Friction test not completed • Table 1(T) if overflight of 5:1 infringement unavoidable • Cleared for AW 139 (6.8t)	5:1: SE & NW access points Misc: No automatic fire-fighting facilities

4. Additional limitations – Nil

These restrictions/changes shall	
remain in force until (unless	Until Further Notice
previously revoked or suspended)	

Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect

Form 09 Rev 01 August 2021