

MODEL QUESTION PAPER

MANUFACTURING TECHNOLOGY FOR AUTOMOBILE COMPONENTS

Time : 3 Hours

Max. Marks : 75

PART A**I. Answer all questions in one word or one sentence****(9 x 1 = 9 Marks)**

Module outcome Cognitive level

1	List any two types of pattern allowances	M 1.04	A
2	Define chaplets used in casting process	M 1.05	R
3	Identify any 2 automobile components made by powder metallurgy	M 1.12	A
4	Shielding gas used for TIG welding is _____	M 2.07	U
5	The horizontal feed in a lathe is controlled by (a) Headstock (b) Apron (c) Cross slide (d) Tailstock	M 3.01	R
6	What is the function of lead screw in lathe	M 3.01	R
7	Which part of shaper provides straight line motion of tool (a) Cross rail (b) Ram (c) Column (d) Table	M 3.03	U
8	Knee is the part of which machine	M 3.06	R
9	Define forging	M 4.02	R

PART B

II. Answer any Eight questions from the following.

(8 x 3= 24 Marks)

Module outcome Cognitive level

1	Explain Sweep pattern	M 1.03	U
2	List any 3 differences between Soldering and Brazing	M 2.11	U
3	Discuss the function of carriage in lathe	M 3.01	U
4	Identify any six components of shaper	M 3.03	A
5	Define Side milling and End milling	M 3.07	U
6	Discuss briefly about Flexible manufacturing system	M 3.09	U
7	List any 3 forging operations	M 4.03	U
8	Differentiate between direct extrusion and indirect extrusion	M4.06	A
9	Define wire drawing	M 4.07	U
10	What you mean by rapid prototyping	M 4.09	U

PART C

III. Answer all questions from the following

(6x 7 = 42 Marks)

Module outcome Cognitive level

1	Define any five casting defects	M 1.08	U
	OR		
2	Illustrate Centrifugal casting process with a neat sketch	M 1.07	U
3	Illustrate Cold chamber die casting process with a neat sketch	M 1.07	A
	OR		
4	Outline the various steps in Powder metallurgy process	M 1.09	A

5	Explain different types of gas welding flames	M 2.09	U
	OR		
6	With a neat sketch, Illustrate the process of Resistance Spot welding	M 2.10	U
7	Define any five sheet metal operations	M 2.03	U
	OR		
8	Outline the process of MIG welding with the help of a neat ketch	M 2.07	U
9	With a neat sketch explain the parts of a drilling machine.	M 3.04	U
	OR		
10	With a neat sketch explain the parts of column and knee type milling machine.	M 3.06	U
11	Illustrate the forging of connecting rod	M 4.04	U
	OR		
12	Illustrate Hot rolling and Sketch any 2 rolling mill configurations	M4.05	U