

TED (10) 4057
(Revision – 2010)

FIFTH SEMESTER DIPLOMA EXAMINATION
MODEL QUESTION PAPER
PRODUCTION & ASSEMBLY TECHNIQUES

(Max. Marks-100)

(Time- 3 Hrs)

PART-A

I Answer the following questions in one or two sentences. Each question carries 2 Marks.

1. List three phases of shop floor control.
2. What is the importance of Quality Assurance ?
3. What do you mean by CMM ?
4. What is the use of logic probe ?
5. Differentiate between maintenance and repair.

(5 x 2 = 10)

PART – B

II Answer any five of the following questions. Each question carry 6 Marks.

1. Distinguish contact and non -contact bar code readers
2. Explain ON line and OFF line inspection?
3. Draw the layout plan of flexible inspection system.
4. Write the procedure for measurement of extra high tension voltages.
5. Write the various information to be included in a Work order
6. Draw the relationship between cost and amount of preventive maintenance.
7. List the problems associated with power supplies.

(5 x 6 = 30)

PART-C

Answer one full question from each unit. Each question carry 15 Marks.

UNIT-1

III Explain various method of Automatic identification. (15)

OR

IV (a).State the concept of DSP. (5)

(b) Illustrate Virtual instrumentation System with a suitable example (10)

UNIT-1I

V Explain six types CMM construction (15)

OR

VI Explain Machine vision System with a diagram. (15)

UNIT-1II

VII Write short note on(a) Logic clip (b)Logic comparator (c) logic analyser (15)

OR

VIII (a) Describe unwanted oscillations and problems associated with oscillations? (15)

UNIT-1V

IX (a) Explain common causes of failure in an Electronic system (10)

(b) Draw the diagram of curve of failure. (5)

OR

X Explain the trouble shooting procedure with a neat diagram. (15)

— --- —