

TED (10) - 4028

Reg.No.....

(REVISION-2010)

Signature.....

SIXTH SEMESTER EXAMINATION IN ENGINEERING/

- MARCH, 2013

MODEL QUESTION PAPER

ADVANCED PRODUCTION PROCESS

PART-A

1. Answer the following questions in one or two sentences. Each question carries 2 marks

1. Define the tool layout of an automatic
2. List types of machining centers
3. List the methods of gear manufacture
4. List the unconventional method of machining
5. Define robotics

PART-B

II. Answer any five of the following. Each question carries 6 marks.

1. Draw the tool layout in sequence for a given set of operations of a work- hexagonal bolt
2. List the advantages of single spindle Vs multi spindle automatics
3. Explain with the diagram the broaching tool details
4. List the advantages and disadvantages of gear hobbling
5. Explain the principle of minimum locating points.
6. Explain the importance of powder metallurgy
7. List different hardware and software for CAD/CAM

(5x6 = 30)

PART-C

Answer one full question from each module. Each question carries 15 marks.

MODULE-1

- III. (a) Sketch a pantograph copying system (5)
(b) Explain the turret lathe indexing mechanism with a neat sketch (10)

OR

- IV (a) Describe requirements of machine centers (5)
(b) Explain hexapod machines (10)

MODULE-2

- V (a) Explain the types of broaching tools (5)
(a) Briefly describe the processing plastics such as extrusion, injection moulding, and blow moulding (10)

OR

- VI (a) Classify the jigs and fixtures (5)
(b) Briefly explain the any two gear generating process (10)

MODULE-3

- VII (a) Classify the abrasives (5)
(b) Explain the basic features of finishing, honing , lapping and super finishing (10)

OR

- VIII (a) Classify the various grinding machines (5)
(b) Explain the mechanical pulverization, electrolytic process, chemical reaction for manufacturing metal powders (10)

MODULE-4

- IX) (a) Classify the N.C machines (5)
(b) Write a part program for drilling ,turning (10)

OR

- X) (a) Define the flexible automation (5)
(b) Briefly describe the basic elements of a NC machines (10)

