

FOURTH SEMESTER DIPLOMA EXAMINATION IN TEXTILE TECHNOLOGY

TEXTILE TESTING AND QUALITY ASSURANCE

[Time : 3 hours

(Maximum marks : 100)

PART –A

(Maximum marks : 10)

I Answer the following questions in one or two sentences. Each question carries 2 marks.

1. Define Statistics.
2. State the term - 2.5 % Span length .
3. Define Young's modulus.
4. State the term - Twist on twist .
5. Define flexural rigidity.

(5*2=10)

PART- B

(Maximum marks: 30)

II Answer any five of the following questions. Each question carries 6 marks.

1. Describe the terms Mean, median and mode.
2. Explain Standard testing atmosphere and standard regain.
3. Explain the features of Digital Fibrograph .
4. Explain the air flow principle.
5. Describe the working of KNOWLES balance.
6. Describe the pendulum lever principle of CRT.
7. Explain the different types of yarn variation.

(5*6=30)

PART- C

(Maximum marks : 60)

(Answer one full question from each unit. Each question carries 15 marks.)

UNIT –I

III (a) State the formula for calculation of standard deviation

3

(b) Calculate the Mean , Mean deviation and Percentage Mean Deviation of the following ten data :

25, 30, 22, 26, 23, 28, 24, 23, 27, 22.

12

OR

- IV (a) State the importance of humidity in textiles. 3
(b) Explain the working of conditioning oven with figure. 12

UNIT – II

- V (a) State the importance of fiber fineness. 3
(b) Explain the method of analysis of Baer sorter diagram 12

OR

- VI (a) Define breaking extension. 3
(b) Describe the procedure of trash % determination using Shirley Trash Analyser with line diagram. 12

UNIT – III

- VII (a) Define twist angle. 3
(b) Explain the working of Lea strength tester with a neat diagram. 12

OR

- VIII (a) State the formula for calculation of Take up % in Take up twist tester. 3
(b) Explain the working of Tension type twist tester with neat sketch. 12

UNIT – IV

- IX (a) Define crimp amplitude. 3
(b) Explain the working of tearing strength tester with a neat sketch 12

OR

- X (a) Describe drape coefficient 3
(b) Explain the working of Shirley crease recovery tester with a figure. 12

=====o=====