

(Revision – 2015)

Reg. No.

SUB CODE: 6102

Signature.

Sixth Semester Diploma Examination In Printing Technology

Quality Management & Standardization

[Maximum Marks : 100]

[Time : 3 Hour]

PART – A

[Maximum Marks : 10]

I. Answer the following question in one or two sentences:

Marks

1. Define ISO.
2. Expand FOGRA.
3. Define Hue error.
4. Recall gloss.
5. Omit Lean Printing.

[5x2=10]

PART – B

[Maximum Marks : 30]

II. Answer any five full questions:

1. Share your idea on IGT Printability testers.
2. Write about the services provided from Graphic Arts & Technical Foundation.
3. Define 'Ghosting'. Explain the factors which influence ghosting.
4. Explain about UGRA/FOGRA digital plate control wedge.
5. Narrate 'Curl Test'. Also explain its test methods.
6. Write the importance of Stiffness test in quality control lab.
7. Narrate about Lean manufacturing concept.

[5x6=30]

PART – C
[Maximum Marks : 60]
[Answer one full question from each unit]

UNIT – I

- III. a) Narrate a note on Print parameters which influence Print quality.
b) Write about merits and de-merits of Instrumental quality evaluation. [7.5+7.5]

OR

- IV. Explain about
 A) ICC
 B) PIA
 C) PIRA [5+5+5]

UNIT – II

- V. What you meant by 'Dot gain'? Explain the factors which influence dot gain. [15]

OR

- VI. Describe the working principle of densitometer with neat a neat diagram. [15]

UNIT – III

- VII. Narrate on the Physical properties of Paper. Also write its importance and test methods. [15]

OR

- VIII. Differentiate Printability with Runnability. [15]

UNIT – IV

- IX. Explain about Seven types of wastes in Lean. [15]

OR

- X. Explain about Color management. Explain its need and importance. [15]

XXXXXXXXXXXXXXXXXX