

TP IT SOLUTIONS

GSTIN:-07CYOPS8925G1ZO

MAIL ID:-tp.solutions2013@yahoo.in

PH:-8950123796

ALL KINDS OF ELECTRONICS, ELECTRICAL, COMPUTERS & GENERAL ORDER SUPPLIERS & SERVICES

Plot No. 724A, ward No. 15, Dev Nagar , kakroi Road , Sonipat-131001

Main Branch:- RZ-667 A, KHASRA NO. 54/6, F/F, GOPAL NAGAR, NAJAF GARH, NEW DELHI-110043

To

The
Commandant,
BN-238

Narela, Delhi

Subject: Replacement of Cartridge Detection Board for HP Laser MFP 136nw Printer and Replacement of Pressure Roller and Servicing of HP 1020 Plus .

R/Sir,

With reference , to the above subject, we are pleased to submit our quotation for the required replacement parts and servicing of the printers as detailed below:-

Descriptions:-

A) HP 1020 Plus Printer - S/L No.: CNCHC03201

1. Lower Pressure Roller – 1 @ Rs. 450 /-
2. Thermal Grease – 1 @ Rs. 350 /-
3. Service Charge – 1 @ Rs. 350 /-

Total: Rs. 1,150 /-

GST @ 18%: Rs. 207 /-

Grand Total: Rs. 1357 /-

B) HP Laser MFP 136nw Printer

1. Cartridge Detection Board – 1 @ Rs. 2,500 /-

Total: Rs. 2,500 /-

GST @ 18%: Rs. 450 /-

Grand Total: Rs. 2,500 /-

Net Payable Amount: Rs. 4,307/-



Thanking You