

Report Period: 2026-06-12 00:00:00 to 2026-06-12 23:59:59 | Generated: 2026-06-13 05:39

1. Production Summary

Total Boxes Produced: 16
Total Quantity Produced: 3644

2. Production Mix

Part Number	Part Name	Total Qty
MOCK-C03-30006-X-SUB	Gamma Switch Right Sub (Long)	800
MOCK-D04-40004-X-SUB	Delta Processor Node Left	800
MOCK-E05-50001-X-SUB	Epsilon Housing Sub Right	520
MOCK-A01-10006-X-SUB	Alpha Subsystem Aux Left	400
MOCK-E05-50003-X-SUB	Epsilon Housing Sub Left	400
MOCK-F06-60001-X-SUB	Zeta Mount Assembly RH	400
MOCK-D04-40001-X-SUB	Delta Processor Node Right	240
MOCK-G07-70001-X-SUB	Omega Framework Sub Left	84

3. Quality & Defects Summary

Defect Type	Incidents	Total Defective Qty
Assembly Error	3	155
Dimension Out of Spec	1	6
Functional Failure	1	56
Other	1	23

4. Operator Output Summary

Operator ID	Total Qty Produced
333	1804
332	1600
566	240

Report Period: 2026-06-12 00:00:00 to 2026-06-12 23:59:59 | Generated: 2026-06-13 05:39

5. Target vs Actual Performance

Part Number	Target Qty	Actual Qty
MOCK-D04-40004-X-SUB	N/A	800
MOCK-C03-30006-X-SUB	N/A	800
MOCK-E05-50001-X-SUB	N/A	520
MOCK-F06-60001-X-SUB	1230	400
MOCK-E05-50003-X-SUB	N/A	400
MOCK-A01-10006-X-SUB	690	400
MOCK-D04-40001-X-SUB	N/A	240
MOCK-G07-70001-X-SUB	N/A	84

6. Current WIP Inventory (In Rack)

Part Number	Total Qty in Rack	Box Count
MOCK-B02-20004-X-SUB	15500	9
MOCK-F06-60001-X-SUB	6000	4
MOCK-A01-10003-X-SUB	5958	4
MOCK-E05-50003-X-SUB	2190	5
MOCK-B02-20005-X-SUB	1750	4
MOCK-A01-10001-X-SUB	1712	5
MOCK-B02-20003-X-SUB	300	1
MOCK-D04-40001-X-SUB	240	2
MOCK-A01-10006-X-SUB	130	1
MOCK-C03-30006-X-SUB	90	1
MOCK-E05-50001-X-SUB	80	2
MOCK-G07-70001-X-SUB	26	2

Report Period: 2026-06-12 00:00:00 to 2026-06-12 23:59:59 | Generated: 2026-06-13 05:39

7. Raw Material Usage (Traceability)

RM Part Number	RM Name	Batches Consumed
MOCK-D04-40001-Y-PRT	Delta Primary Node	4
MOCK-E05-50001-Y-PRT	Epsilon Housing Right	3
MOCK-G07-70001-Y-PRT	Omega Anchor Left	3
MOCK-C03-30006-Y-PRT	Gamma Switch Long Right	2
MOCK-A01-10006-Y-PRT	Alpha Core (Auxiliary) Left	1
MOCK-E05-50003-Y-PRT	Epsilon Housing Left	1
MOCK-F06-60001-Y-PRT	Zeta Mount RH	1

8. Downtime Summary

Operator ID	Downtime Reasons	Total Duration (Mins)
534	Maintenance,Other: Power Outage,Material Shortage	136.0
333	Other: System Update,Quality Issue,Operator Absence,...	89.0
332	Tool Change,Maintenance,Quality Issue,Operator Absence	85.0
533	Other: Cleaning,Operator Break,Other: Meeting,Setup ...	74.0