SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

photoeye offset: cause

Section ID: SYN-SEC-001

Logical document: SYN-DOC-001 | Version: 1.0 | Logical page: 1

Equipment: SYN-EQ-001, SYN-EQ-008

Failure mode: SYN-FM-001 | Referenced fixes: SYN-FIX-001

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-001: Fictional fault: container not detected. The seeded simulator correction is SYN-FIX-001 (Simulator correction: photoeye offset), using SYN-PART-001. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

photoeye offset: contrast

Section ID: SYN-SEC-002

Logical document: SYN-DOC-001 | Version: 1.0 | Logical page: 2

Equipment: SYN-EQ-001, SYN-EQ-008

Failure mode: SYN-FM-001 | Referenced fixes: SYN-FIX-001, SYN-FIX-016

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-001: Fictional fault: container not detected. The seeded simulator correction is SYN-FIX-001 (Simulator correction: photoeye offset), using SYN-PART-001. SYN-FIX-016 (Simulator alternate-cause check: carton sensor alignment) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

guide spacing drift: cause

Section ID: SYN-SEC-003

Logical document: SYN-DOC-001 | Version: 1.0 | Logical page: 3

Equipment: SYN-EQ-001, SYN-EQ-009

Failure mode: SYN-FM-002 | Referenced fixes: SYN-FIX-002

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-002: Fictional fault: container position inconsistent. The seeded simulator correction is SYN-FIX-002 (Simulator correction: guide spacing drift), using SYN-PART-002. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

guide spacing drift: contrast

Section ID: SYN-SEC-004

Logical document: SYN-DOC-001 | Version: 1.0 | Logical page: 4

Equipment: SYN-EQ-001, SYN-EQ-009

Failure mode: SYN-FM-002 | Referenced fixes: SYN-FIX-002, SYN-FIX-017

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-002: Fictional fault: container position inconsistent. The seeded simulator correction is SYN-FIX-002 (Simulator correction: guide spacing drift), using SYN-PART-002. SYN-FIX-017 (Simulator alternate-cause check: reject confirmation mismatch) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

timing recipe mismatch: cause

Section ID: SYN-SEC-005

Logical document: SYN-DOC-001 | Version: 1.0 | Logical page: 5

Equipment: SYN-EQ-002, SYN-EQ-009

Failure mode: SYN-FM-003 | Referenced fixes: SYN-FIX-003

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-003: Fictional fault: transfer timing inconsistent. The seeded simulator correction is SYN-FIX-003 (Simulator correction: timing recipe mismatch), using SYN-PART-003. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

timing recipe mismatch: contrast

Section ID: SYN-SEC-006

Logical document: SYN-DOC-001 | Version: 1.0 | Logical page: 6

Equipment: SYN-EQ-002, SYN-EQ-009

Failure mode: SYN-FM-003 | Referenced fixes: SYN-FIX-003, SYN-FIX-018

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-003: Fictional fault: transfer timing inconsistent. The seeded simulator correction is SYN-FIX-003 (Simulator correction: timing recipe mismatch), using SYN-PART-003. SYN-FIX-018 (Simulator alternate-cause check: print reference drift) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

cap feed orientation: cause

Section ID: SYN-SEC-007

Logical document: SYN-DOC-002 | Version: 1.0 | Logical page: 1

Equipment: SYN-EQ-002, SYN-EQ-010

Failure mode: SYN-FM-004 | Referenced fixes: SYN-FIX-004

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-004: Fictional fault: cap presentation inconsistent. The seeded simulator correction is SYN-FIX-004 (Simulator correction: cap feed orientation), using SYN-PART-004. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

cap feed orientation: contrast

Section ID: SYN-SEC-008

Logical document: SYN-DOC-002 | Version: 1.0 | Logical page: 2

Equipment: SYN-EQ-002, SYN-EQ-010

Failure mode: SYN-FM-004 | Referenced fixes: SYN-FIX-004, SYN-FIX-019

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-004: Fictional fault: cap presentation inconsistent. The seeded simulator correction is SYN-FIX-004 (Simulator correction: cap feed orientation), using SYN-PART-004. SYN-FIX-019 (Simulator alternate-cause check: simulated belt tracking) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

label reference offset: cause

Section ID: SYN-SEC-009

Logical document: SYN-DOC-002 | Version: 1.0 | Logical page: 3

Equipment: SYN-EQ-003, SYN-EQ-010

Failure mode: SYN-FM-005 | Referenced fixes: SYN-FIX-005

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-005: Fictional fault: label position inconsistent. The seeded simulator correction is SYN-FIX-005 (Simulator correction: label reference offset), using SYN-PART-005. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

label reference offset: contrast

Section ID: SYN-SEC-010

Logical document: SYN-DOC-002 | Version: 1.0 | Logical page: 4

Equipment: SYN-EQ-003, SYN-EQ-010

Failure mode: SYN-FM-005 | Referenced fixes: SYN-FIX-005, SYN-FIX-020

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-005: Fictional fault: label position inconsistent. The seeded simulator correction is SYN-FIX-005 (Simulator correction: label reference offset), using SYN-PART-005. SYN-FIX-020 (Simulator alternate-cause check: foil presentation mismatch) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

carton sensor alignment: cause

Section ID: SYN-SEC-011

Logical document: SYN-DOC-002 | Version: 1.0 | Logical page: 5

Equipment: SYN-EQ-003

Failure mode: SYN-FM-006 | Referenced fixes: SYN-FIX-006

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-006: Fictional fault: carton presence intermittent. The seeded simulator correction is SYN-FIX-006 (Simulator correction: carton sensor alignment), using SYN-PART-006. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

carton sensor alignment: contrast

Section ID: SYN-SEC-012

Logical document: SYN-DOC-002 | Version: 1.0 | Logical page: 6

Equipment: SYN-EQ-003

Failure mode: SYN-FM-006 | Referenced fixes: SYN-FIX-006, SYN-FIX-021

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-006: Fictional fault: carton presence intermittent. The seeded simulator correction is SYN-FIX-006 (Simulator correction: carton sensor alignment), using SYN-PART-006. SYN-FIX-021 (Simulator alternate-cause check: virtual fill recipe mismatch) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

reject confirmation mismatch: cause

Section ID: SYN-SEC-013

Logical document: SYN-DOC-003 | Version: 1.0 | Logical page: 1

Equipment: SYN-EQ-004

Failure mode: SYN-FM-007 | Referenced fixes: SYN-FIX-007

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-007: Fictional fault: reject confirmation absent. The seeded simulator correction is SYN-FIX-007 (Simulator correction: reject confirmation mismatch), using SYN-PART-007. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

reject confirmation mismatch: contrast

Section ID: SYN-SEC-014

Logical document: SYN-DOC-003 | Version: 1.0 | Logical page: 2

Equipment: SYN-EQ-004

Failure mode: SYN-FM-007 | Referenced fixes: SYN-FIX-007, SYN-FIX-022

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-007: Fictional fault: reject confirmation absent. The seeded simulator correction is SYN-FIX-007 (Simulator correction: reject confirmation mismatch), using SYN-PART-007. SYN-FIX-022 (Simulator alternate-cause check: checkweight reference drift) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

print reference drift: cause

Section ID: SYN-SEC-015

Logical document: SYN-DOC-003 | Version: 1.0 | Logical page: 3

Equipment: SYN-EQ-004

Failure mode: SYN-FM-008 | Referenced fixes: SYN-FIX-008

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-008: Fictional fault: print position inconsistent. The seeded simulator correction is SYN-FIX-008 (Simulator correction: print reference drift), using SYN-PART-008. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

print reference drift: contrast

Section ID: SYN-SEC-016

Logical document: SYN-DOC-003 | Version: 1.0 | Logical page: 4

Equipment: SYN-EQ-004

Failure mode: SYN-FM-008 | Referenced fixes: SYN-FIX-008, SYN-FIX-023

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-008: Fictional fault: print position inconsistent. The seeded simulator correction is SYN-FIX-008 (Simulator correction: print reference drift), using SYN-PART-008. SYN-FIX-023 (Simulator alternate-cause check: leaflet presence alignment) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

simulated belt tracking: cause

Section ID: SYN-SEC-017

Logical document: SYN-DOC-003 | Version: 1.0 | Logical page: 5

Equipment: SYN-EQ-005

Failure mode: SYN-FM-009 | Referenced fixes: SYN-FIX-009

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-009: Fictional fault: transfer position drifting. The seeded simulator correction is SYN-FIX-009 (Simulator correction: simulated belt tracking), using SYN-PART-009. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT

SYNTHETIC TRAINING ONLY - NOT AN OEM MANUAL

simulated belt tracking: contrast

Section ID: SYN-SEC-018

Logical document: SYN-DOC-003 | Version: 1.0 | Logical page: 6

Equipment: SYN-EQ-005

Failure mode: SYN-FM-009 | Referenced fixes: SYN-FIX-009, SYN-FIX-024

BEGIN SECTION TEXT

Fictional training evidence for SYN-FM-009: Fictional fault: transfer position drifting. The seeded simulator correction is SYN-FIX-009 (Simulator correction: simulated belt tracking), using SYN-PART-009. SYN-FIX-024 (Simulator alternate-cause check: case stop reference drift) is a plausible symptom-overlap decoy; it does not resolve this seeded cause. Synthetic simulator only; no real maintenance authorization. Follow site-approved procedures and qualified review.

END SECTION TEXT