BUREAU VERITAS

BV No. 0101447

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date	Inspection Time	Previous Sticker
	QATIF	JULY 29, 202	—	No. 10124 Issued By R.V
Department / Contractor	**Equipment Number**	**Equipment Location**	**Inspection Result**	**New Sticker No.**
SUDIAJR	S28S6-107	RSG 785	☑ Pass ☐ Fail	BV-21-1559
Manufacturer	**Model**	**Capacity / Type**	**Equipment Serial Number**	**Sticker Expiration Date**
GENIE	S85	227KG / MEWP	S85D-807	JAN 28, 2022

Above Equipment was inspected by bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective action are listed below . Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection and function test for Boom supported Elevating work Plat form. As per as S.Aramco GI 7-036, ANSI 92.5 Boom	
2	Follow proper PM	

RECEIVER NAME: Vishnu SIGNATURE: INSPECTOR NAME: M. Omar

BADGE#: TELEPHONE No.: TELEPHONE No.: 18-0009

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy - 2nd Copy - Inspector Agency