BUREAU VERITAS

BV No. 09435

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date	Inspection Time	Previous Sticker
	RAS ALKHAIR	APRIL 08, 2021	—	No. 10981 Issued By [illegible]
Department / Contractor	**Equipment Number**	**Equipment Location**	**Inspection Result**	**New Sticker No.**
SUDITJR	S38SJP-155	RSJC	☑ Pass ☐ Fail	BV-21-015
Manufacturer	**Model**	**Capacity** / **Type**	**Equipment Serial Number**	**Sticker Expiration Date**
JLG	1200SJP	500LBS / Manlift	0300236079	OCT 07, 2021

Above Equipment Was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's ASME and API standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection and function test for	
	Boom supported elevating work platform	
	As per AS Saudi Aramco GI 7.301 ANSI 92.5	
	"PASS"	

RECEIVER NAME: JOEL SIGNATUE: [signature] INSPECTOR NAME: [illegible]

BADGE#: 11230 TELEPHONE No.: 0551897903 TELEPHONE No.: [illegible]

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy -2nd Copy - Inspector Agency