BUREAU VERITAS

BV No. 235669

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date	Inspection Time	Previous Sticker
	ABGB	JUNE 08.2023	9:00	No. 21-7309 Issued By BV
Department / contractor	**Equipment Number**	**Equipment Location**	**Equipment Result**	**New Sticker No.**
SUHJR	S20AJ-179	SPARK	☑ Pass ☐ Fail	BV-21-9653
Manufacturer	**Model**	**Capacity / Type**	**Equipment Serial Number**	**Sticker Expiration Date**
JL	600AJ	500LBS / NEWP	B300002233	DEC 07.2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI`s , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection and function test for	
	Boom supported elevating work platform	
	As per AS S-ARAMCO GI 7.03 and ANSI 92.5	
	'Pass'	

RECEIVER NAME: THASEER SIGNATURE: INSPECTOR NAME: Mohammad

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 18-0029

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency