BUREAU VERITAS

**BV No.** 236987

| LIFTING EQUIPMENT INSPECTION REPORT | Area | Inspection Date | Inspection Time | Previous Sticker |
|---|---|---|---|---|
| | DAMMAM | 24-OCT-2023 | 15:30 | No. BV-21-7766 Issued By B |
| **Department / contractor** | **Equipment Number** | **Equipment Location** | **Equipment Result** | **New Sticker No.** |
| SUDHIR RENTALS | S28SJ-310 | CLIENT YARD | ☑ Pass ☐ Fail | BV-21-8600 |
| **Manufacturer** | **Model** | **Capacity / Type** | **Equipment Serial Number** | **Sticker Expiration Date** |
| JLG | 860 SJ | 227 kg / MEWP | B300002162 | 23-APR-2024 |

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards

Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Colu

| No. | DEFICIENCIES | CORRECTIVE ACTION TAKEN |
|---|---|---|
| | Periodic visual insp + functional test Carried out on | |
| | BOOM Supported EWP as per ARAMCO GI 7.030, | |
| | ANSI A92.5 and Equipment found satisfactory at the | |
| | time of Insp. | |

RECEIVER NAME: ARIF SIGNATURE: INSPECTOR NAME: JEETH / 800191

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 055048609

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Age