


Linearity wants a small contrast, level wants a large one. One permeability field cannot do both.

(a) The well's linearity is set by the contrast
negative = the model softens as it goes



(b) But the pressure LEVEL needs a large contrast
with $k_{p,min}$ pinned at $1e-15$ these are one knob

