



LTspice Shortcuts:

These will save you a lot of time!

V – Voltage Source

R – Resistor

C – Capacitor

L - Inductor

D – Diode

G – Ground

CTRL+R – Rotate Component (After clicking move)

S - Spice Directive

F9 – Undo

SHIFT+F9 – Redo

=====

Shortcuts can be created and changed at:

Tools >> Control Panel >> Drafting Options >> Hot Keys[*]