Variables | Expressions

Name	Type	Value	Location
IDU2	unsigned int	0xBF48 (Hex)	0x03FA
IDU3	unsigned int	0xBF48 (Hex)	0x03F8
StatusRegister_U2	unsigned char	0x0C (Hex)	0x03FC
StatusRegister_U3	unsigned char	0x0C (Hex)	0x03FD

spi.c | serial_flash.c | main.c

```
 4 void InitializeSPI()
 5 {
 6
 7     SET_USCIA0_MISO_AS_AN_INPUT;
 8     SET_USCIA0_MOSI_AS_AN_OUTPUT;
 9
10     UCA0CTL1 = UCSWRST;          // Set up the SPI mode
11
12     P1SEL  = BIT1|BIT2|BIT4;     // Set pins 1, 2, and 4 to comm mode
13     P1SEL2 = BIT1|BIT2|BIT4;
14
15     // Mode 0, MSB first, 8-bit SPI master, three-pin mode
16     UCA0CTL0 |= UCCKPH | UCMSB | UCMST | UCSYNC;
17
18     UCA0CTL1 |= UCSSEL_2;        // Use SMCLK, keep SW reset
19
20     UCA0BR0 |= 0x02;             // Divide provided (SMCLK) clock by 2
21     UCA0BR1 |= 0x00;             // For 16MHz, this should divide to 8Mhz
22
23     UCA0MCTL = 0;                // No modulation
24
25     UCA0CTL1 &= ~UCSWRST;        // Clear SW reset, resume operation
26
27 }
28
29 void SPISendByte(unsigned char SendValue)
30 {
31
32     UCA0TXBUF = SendValue;           // Write to the transaction buffer
33     while(UCA0STAT&BIT0);            // wait while busy bit is high
34
35 }
36
37 unsigned char SPIReceiveByte()
38 {
39
40     UCA0TXBUF = 0x00;                // Send dummy to transmit buffer
41     while(UCA0STAT&BIT0);            // wait while busy bit is high
42     return UCA0RXBUF;                // Return receive buffer
43
44 }
```