2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Willard School

Governance DISTRICT Report Type Elementary Address 1930 E. Elkhart St. Enrollment 752 '00-04' Philadelphia, Pa 19134 Grade Range 215-291-4714 / 215-291-4161 Phone/Fax

Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Willard Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	00.46%	\$242,339	\$52,429,167
Building	00.32 %	\$160,786	\$50,256,330
Grounds	03.75 %	\$81,553	\$2,172,837

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.12 %	\$3,202	\$2,759,389
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$3,589,904
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,751,671
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$141,028
Interior Doors (Classroom doors)	00.00 %	\$0	\$341,386
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,634,957
Plumbing Fixtures	00.00 %	\$0	\$1,314,969
Boilers	00.00 %	\$0	\$1,815,863
Chillers/Cooling Towers	00.00 %	\$0	\$2,380,949
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$4,181,250
Heating/Cooling Controls	00.00 %	\$0	\$1,313,024
Electrical Service and Distribution	00.00 %	\$0	\$943,432
Lighting	00.00 %	\$0	\$3,373,011
Communications and Security (Cameras, Pa System and Fire Alarm)	12.47 %	\$157,584	\$1,263,420

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.