2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

De Burgos School

Governance DISTRICT Report Type Elementarymiddle

Address 401 W. Lehigh Ave. Enrollment 872
Philadelphia, Pa 19133 Grade Range '00-08'

Phone/Fax 215-291-4065 / 215-291-4084 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Deburgos Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	00.64%	\$414,760	\$64,701,308
Building	00.48 %	\$316,304	\$65,830,634
Grounds	08.45 %	\$95,807	\$1,133,164

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$2,267,750
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$4,853,665
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$2,368,315
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$190,675
Interior Doors (Classroom doors)	00.00 %	\$0	\$461,565
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$2,210,515
Plumbing Fixtures	00.00 %	\$0	\$1,777,880
Boilers	00.00 %	\$0	\$2,455,105
Chillers/Cooling Towers	00.00 %	\$0	\$3,219,120
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$5,653,185
Heating/Cooling Controls	00.00 %	\$0	\$1,775,250
Electrical Service and Distribution	00.00 %	\$0	\$1,275,550
Lighting	00.00 %	\$0	\$4,560,420
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$1,708,185

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.