2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Levering School

Governance DISTRICT Report Type Middle
Address 6000 Ridge Ave. Enrollment 308
Philadelphia, Pa 19128 Grade Range '06-08'

Phone/Fax 215-487-7600 / 215-487-7505 Admissions Category Special Admit

Website Www.Philasd.Org/Schools/Amynw Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	45.01%	\$16,283,630	\$36,176,736
Building	45.07 %	\$15,854,918	\$35,179,323
Grounds	25.25 %	\$301,788	\$1,195,417

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,101,746
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,564,322
Windows (Shows functionality of exterior windows)	105.69 %	\$1,322,405	\$1,251,245
Exterior Doors (Shows condition of exterior doors)	128.59 %	\$129,537	\$100,739
Interior Doors (Classroom doors)	172.15 %	\$419,812	\$243,857
Interior Walls (Paint and Finishes)	06.96 %	\$81,287	\$1,167,875
Plumbing Fixtures	09.36 %	\$87,898	\$939,302
Boilers	80.09 %	\$1,038,883	\$1,297,098
Chillers/Cooling Towers	64.37 %	\$1,094,740	\$1,700,748
Radiators/Unit Ventilators/HVAC	160.01 %	\$4,779,063	\$2,986,730
Heating/Cooling Controls	158.90 %	\$1,490,382	\$937,913
Electrical Service and Distribution	109.21 %	\$735,951	\$673,908
Lighting	34.13 %	\$822,297	\$2,409,393
Communications and Security (Cameras, Pa System and Fire Alarm)	45.55 %	\$411,044	\$902,480

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.