2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Harrington School

Governance DISTRICT Report Type Elementarymiddle

Address 5300 Baltimore Ave. Enrollment 492
Philadelphia, Pa 19143 Grade Range '00-08'

Phone/Fax 215-471-2914 / 215-471-5087 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Harrington Turnaround Model N/A

Building/System FCI Tiers

| Facility Condition Index (FCI) = Cost of Assessed Deficiencies | | | | | | | |
|--|-------------------------------|---|--|--|--|--|--|
| raciiit | y Condition index (FCI) | Replacen | Replacement Value | | | | |
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% | | | |
| Buildings | | | | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. | | | |
| Systems | | | | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program | | | |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------|---------|--------------|------------------|
| Overall | 46.47% | \$16,011,229 | \$34,454,153 |
| Building | 46.27 % | \$15,466,645 | \$33,424,654 |
| Grounds | 52.90 % | \$544,584 | \$1,029,499 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|---|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 89.67 % | \$887,966 | \$990,206 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 34.02 % | \$835,006 | \$2,454,515 |
| Windows (Shows functionality of exterior windows) | 150.52 % | \$1,802,775 | \$1,197,665 |
| Exterior Doors (Shows condition of exterior doors) | 07.11 % | \$6,854 | \$96,425 |
| Interior Doors (Classroom doors) | 73.81 % | \$172,280 | \$233,415 |
| Interior Walls (Paint and Finishes) | 02.17 % | \$25,701 | \$1,181,705 |
| Plumbing Fixtures | 17.61 % | \$158,356 | \$899,080 |
| Boilers | 63.14 % | \$783,903 | \$1,241,555 |
| Chillers/Cooling Towers | 48.83 % | \$794,940 | \$1,627,920 |
| Radiators/Unit Ventilators/HVAC | 85.12 % | \$2,433,562 | \$2,858,835 |
| Heating/Cooling Controls | 158.90 % | \$1,426,567 | \$897,750 |
| Electrical Service and Distribution | 93.15 % | \$600,840 | \$645,050 |
| Lighting | 03.39 % | \$78,070 | \$2,306,220 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 21.08 % | \$182,095 | \$863,835 |

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.