2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Day LSH School

Governance DISTRICT Report Type Elementarymiddle

Address 6324 Crittenden St. Enrollment

Philadelphia, Pa 19138 Grade Range '00-08'
Phone/Fax 215-276-5250 / 215-276-5817 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Day Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	06.74%	\$1,198,022	\$17,776,188
Building	07.02 %	\$1,042,434	\$14,857,712
Grounds	05.33 %	\$155,587	\$2,918,476

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	04.22 %	\$43,990	\$1,042,329
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$785,433
Windows (Shows functionality of exterior windows)	58.86 %	\$201,846	\$342,904
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$42,014
Interior Doors (Classroom doors)	00.00 %	\$0	\$94,594
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$422,906
Plumbing Fixtures	00.00 %	\$0	\$794,490
Boilers	02.47 %	\$11,600	\$469,700
Chillers/Cooling Towers	00.00 %	\$0	\$615,868
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$1,081,542
Heating/Cooling Controls	158.90 %	\$539,690	\$339,633
Electrical Service and Distribution	00.00 %	\$0	\$244,033
Lighting	00.00 %	\$0	\$872,479
Communications and Security (Cameras, Pa System and Fire Alarm)	33.29 %	\$108,796	\$326,802

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.