2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

GAMP School

GovernanceDISTRICTReport TypeMiddlehighAddress2136 W. Ritner St.Enrollment572Philadelphia, Pa 19145Grade Range'05-12'Phone/Fax215-952-8589 / 215-952-6544Admissions CategorySpecial Admit

Website Www.Philasd.Org/Schools/Gamp Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	09.75%	\$4,275,537	\$43,835,427
Building	09.33 %	\$4,038,466	\$43,304,735
Grounds	44.25 %	\$237,072	\$535,700

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,454,803
Exterior Walls (Shows condition of the structural condition of the exterior facade)	26.51 %	\$968,684	\$3,653,879
Windows (Shows functionality of exterior windows)	22.60 %	\$403,692	\$1,786,044
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$121,017
Interior Doors (Classroom doors)	08.55 %	\$25,046	\$292,945
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,322,006
Plumbing Fixtures	02.02 %	\$22,738	\$1,128,379
Boilers	00.00 %	\$0	\$1,558,198
Chillers/Cooling Towers	08.37 %	\$170,906	\$2,043,101
Radiators/Unit Ventilators/HVAC	16.62 %	\$596,415	\$3,587,945
Heating/Cooling Controls	20.69 %	\$233,135	\$1,126,710
Electrical Service and Distribution	00.00 %	\$0	\$809,562
Lighting	18.39 %	\$532,253	\$2,894,393
Communications and Security (Cameras, Pa System and Fire Alarm)	46.76 %	\$506,991	\$1,084,145

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.