### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **Swenson High School**

Governance DISTRICT Report Type High Address 2750 Red Lion Rd. Enrollment 664 '09-12' Philadelphia, Pa 19114 **Grade Range** 215-961-2009 / 215-961-2081 Admissions Category Phone/Fax Citywide Website Www.Philasd.Org/Schools/Swenson Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	23.40%	\$21,475,560	\$91,788,823
Building	24.10 %	\$20,887,621	\$86,676,820
Grounds	10.42 %	\$587,939	\$5,645,072

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	02.34 %	\$109,238	\$4,665,777
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.05 %	\$3,229	\$6,285,468
Windows (Shows functionality of exterior windows)	163.57 %	\$3,832,852	\$2,343,297
Exterior Doors (Shows condition of exterior doors)	156.98 %	\$450,716	\$287,110
Interior Doors (Classroom doors)	89.37 %	\$577,729	\$646,427
Interior Walls (Paint and Finishes)	04.55 %	\$103,327	\$2,271,090
Plumbing Fixtures	16.38 %	\$889,475	\$5,429,297
Boilers	14.29 %	\$458,527	\$3,209,784
Chillers/Cooling Towers	00.00 %	\$0	\$4,208,651
Radiators/Unit Ventilators/HVAC	20.49 %	\$1,514,373	\$7,390,927
Heating/Cooling Controls	22.01 %	\$510,826	\$2,320,947
Electrical Service and Distribution	60.70 %	\$1,313,906	\$2,164,498
Lighting	61.68 %	\$3,677,794	\$5,962,255
Communications and Security (Cameras, Pa System and Fire Alarm)	43.53 %	\$972,097	\$2,233,267

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.